

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1410)

Set ¼ sec. post, from which
A Fir 20" dia., bears S.82°W., 134 lks. dist.
A Fir 12" dia., bears N.73°E., 108 lks. dist.

Germond - Field Book 15 Page 29 (Also see Vol. 2 Page 266) - (date - 1909?* this year appears in the FB & on surveys just prior to the Vol. 2 entry and a 1911 date after the Vol 2 entry)

Set S. Stone 5"x8"x20" for ¼ cor. secs. 4 & 5*
I reset ¼ cor. bet secs. 4 and 5 as follows:
Red Fir 8" N.28°05'E., 21.½ lks.
Red Fir 6" S.19°30'W., 22½ lks.
(N.B.(?) Cor. not set at either wit. tree point as a great discrepancy is found.) *added 4/14/2011 DCSO JC

J.W. Cole - For: W.C. Sagaberd and J. Grimm - Jan. 1924 - Vol. 3 Page 176 and Field Book 52 Page 20

I found a sandstone marked ¼ S C.S., from which a
Fir 10" S.21°W., 14.4 ft.
Fir 12' N.24°30'E., 13.5 ft.
Stump of 24" Fir, no scribe marks visible bears N.72°E., 62.9 ft.
No trace of other Govt. BT.
I believe this corner was renewed by M.B. Germond but not recorded. (See entry before this one.)

Douglas Co. Surveyors Office - Bruce Rogers, Deputy, Stone and Stoffel, crew - March 1965 - C.S. File 53/101-36

Found - Sandstone mkd. CS ¼ S.
10" Fir now 18" snag, chopped out, shows good scribing.
12" Fir now 19" N.24°E. 13.5 ft rescribed ¼ S4 CS BT
Set Iron rod on South side of stone.
New BT - 12" D.Fir S.39°W., 29.3 ft. mkd. ¼ S5 CS BT.

Survey by Donald Peel - For: Weyerhaeuser Co. - Feb. 1992 - M 114-60

Condition Report Only
Found - 8" x 4" x 8" above ground stone, etched "¼S" on North face and "CS" on top and "¼" on South face.
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias	Description

<p>5/8" rebar on South edge of stone. Used center of stone for corner point. 5 ft. high 20" Fir stump N.27¼°E., 14.2 ft., closed face. 27" Fir S.41½°W., 29.2 ft., closed face, BLM tag.</p>	
<p>Daniel Baker, For Weyerhaeuser, Feb. 1996 M124-13 -----</p>	
Found -	<p>8"x 4"x 8" above ground stone etched "1/4S" on north face and "CS" on top and "1/4" on south face. 5/8" iron rod alongside south side of stone - 1965 Douglas Co. 20" Fir stump, N.27¼°E., 14.2 ft. - 5 ft. high w/closed face; record: N.28°05'E., 21.5 lks. - Germond, book 15 page 29. Rotten stump, S.20°W., 14.3 ft. - scribe visible rec: S.19½°W., 22.5 lks. Germond, book 15, pg 29. 28" Fir, S.41½°W., 29.2 ft. to spike set side center - closed face; record: S.39°W., 29.3 ft. 1965 Do. County.</p>
New -	<p>9" Fir, S.35°E. 15.2 ft to "W" Nail, scribed "¼ S4 BT" 21" Fir, N.23°W., 13.6 ft. to "W" Nail, scribed "¼ S5 BT"</p>
<p>DCSO-GIS Corner visitation - 10/17/2005 - Typed: 1/13/2011 - C.S. File 67/33-1 -----</p>	
Monument -	<p>Stone w/rebar alongside Comment - stumps only</p>
<p>Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Garrett McGraw - April 14, 2011 -C.S. File 67/33-31 -----</p>	
Found -	<p>A 5"x8"x20" tall sandstone marked "CS" on top, "¼ S" on North face, and "¼" on south face (previously described as 4"x8"x8") First found by Cole in 1924, probably set by Germond (date unknown) Stone is set plumb and protrudes approx 12" above ground. From 1965, a ¾" dia., iron rod firmly set on south edge of, and slightly lower than above found stone. 1855 OBT: A fir 12" dia., now a very rotted approximately 24" dia., 2 ft. tall fir stump with the scribing "BT" visible on intact remains of blaze; bears N.71½°E., 64.6 ft. (rec. N.73°E., 71.3 ft.)</p>
<p>continued next page</p>	

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Germond BT: A R.Fir 8" now 17" DBH 5 ft. tall D.Fir stump with a fully healed double blaze; bears N.28°E., 14.2 ft. (as per record) 1924 renewal notes Germond BT & the one OBT.

1965 BT: A 12" D.Fir now a 28" DBH 6 ft. tall D.Fir stump with a fully healed single blaze; bears S.42°W. 29.3 ft. (rec. S.39°W., 29.3 ft.)

1996 BT: A 9" Fir now 10" dia., 20" tall D.Fir stump with a rotted blaze, still showing the scribing "BT", "W" nail not seen. The center of the root crown (CRC) of the stump bears S.29½°E., 16.0 ft. (Rec. S.35°E., 15.2 ft. to "W" nail)

1996 BT: 21" Fir now a 22" DBH 4 ft. tall D.Fir stump with a partially healed single blaze with the scribing "/4 S5 BT" visible and having a "W" nail below the face; bears N.19°W., 13.7 ft. to CRC N.17½°W., 13.1 ft. to "W" nail (rec. N.23°W., 13.6 ft. to "W" nail)

Germond's field notes reveal he set the sandstone monument when both orig. BTs were in evidence. He fd discrepancies from the orig. rec. but was able to set the corner satisfactorily using the OBTs.

New - 13" DBH D.Fir scribed "¼ S4 CS" "BT" on a double blaze; bears N.77½°E., 20.9 ft.

3" DBH D.Fir scribed "X" "CS BT" on a high-low blaze; bears S.55°E., 11.4 ft.

7" DBH D.Fir scribed "¼ S5 CS" "BT" on a double blaze; bears S.55¼°W., 21.6 ft.

8" DBH madrone scribed "¼ S5 CS" "BT" on a double blaze; bears N.12°W., 30.8 ft.

Note - Monument is near top of steep NE slope with older reprod (mainly fir) forest to north and a newer clear-cut to south. A steel fence post is set approx. 0.5 ft. south from the fd stone monument. Compass decl. 15¾°E.