

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1404)

Set ¼ sec. post, from which
A Fir 24" dia., bears S.58°W., (?) lks. dist.
A Fir 24" dia., bears N.45°E., 141 lks. dist.

J.W. Cole, Co. Surveyor - Wit: W.A. Sagaberd; J. Sagaberd; J. Grimm - Jan. 4-10, 1924 - Vol. 3 Page 176 and Field Book 52 Page 24 (and "old" corner book, Page 18)

I renewed this corner at a point where I found a Fir stake marked ¼S CS, presumably set by Germond, from which
A Fir 30" dia., chopped open by Germond but scribe marks visible at this time, bears N.45°W., 93.0 ft.
No trace of other BT.
I marked:
A Fir 12", S.5°00'E., 12.0 ft. ¼S CS BT.

Wilford N. Haines - For Harold Woolley - Feb. 1959 - RM 1-29

Set Lot Marker.
Found - Orig. 30" Fir N.43°21'E., 138 lks.
12" Fir by Cole, down, S.6°57'W., 12.0 ft.
Scribed -12" B.Oak S.57°07'E., 8.7 ft.
16" Fir N.34°13'W., 40.4 ft.

Douglas Co. Surveyors Office - A.Vic Cangie and Mike Tompkins, crew - Nov. 22, 1976 - C.S. File 59/26-17

Found - Haines T-Iron and washer at corner point.
A 12" now 18" B.Oak bears S.57°E., 8.7 ft. Tree is alive but in poor condition. Shows healed blaze.
A 16" now 24" Fir bears N.30½°W., (Rec. N.34°13'W.), 40.4 ft. Healthy and shows healed blaze.
Set a 1" x 30" I.P. with brass cap stamped:
Douglas Co. Surveyor
T 22 S
1/4
S 4 | S 3
R 5 W

We replace found T-Iron on North side of brass cap.
New BT - A 16" R.Cedar bears N.3°E., 27.5 ft. mkd. ¼ S3 CSBT.
Corner lies approx. 50 ft. South of a SW draw in an old E-W fence.

continued next page

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 4

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

<p>Fd. OK, Sept. 1993, D.Baker, M 118-10 Fd. OK, Oct. 1995, D.Baker, M 119-77</p>
<p>DCSO-GIS Corner visitation - 10/18/2005 - Typed: 1/18/2011 - C.S. File 67/33-1</p> <p>-----</p> <p>Monument - 1¼" IP W/BC; T-iron alongside Comment - 2 live trees</p>
<p>Douglas Co. Surveyors Office - Stephen Flause - Mike Koch - Garrett McGraw - Jason Martin - 4/15/2011 - C.S. 67/33-38</p> <p>-----</p> <p>Found - (1976) 2½" dia., brass cap (properly mkd) on a 1" I.D. iron pipe, is firmly set and protrudes 6" above ground. A 1"x1" Haines "T" iron with brass ID washer at top (1959) is set on North edge of and slightly lower than BC monument. (Orig.) A Fir, 24" dia., now 38" dia., 3 ft. tall fir stump with the scribing "¼ S3 BT" visible on a previously opened single blaze; bears N.43°E., 91.7 ft. (orig. rec. N.45°E., 93.1 ft) 1924 BT gone. (1959) A 12" B.Oak now a 29" DBH B.Oak (top broken out but now healed & growing well) with a fully healed single blaze; bears S.50½°E., 8.7 ft. (rec. S.57°E., 8.7 ft., this bearing is possibly a face meas.) (1959) A 16" fir now a 32" DBH 7 ft tall D.Fir stump with a fully healed single blaze; bears N.30½°W., 40.4 ft. (this agrees with 1976 record, 1959 record is N.34¼°W., 40.4 ft.) (1976) A 16" R.Cedar, now 29" DBH R.Cedar with a fully healed single blaze; bears N.3°E., 27.5 ft. (as per rec) New BTs- An 8" DBH D.Fir scribed "¼ S4 CS" "BT" on a double blaze; bears S.31½°W., 36.3 ft. A 5" DBH D.Fir scribed "X" "CSBT" on a high-low blaze; bears N.53°W., 22.0 ft. Note - Corner is on moderate, rolling, NW slope on old second growth forest. South timberline 200 ft. West from forest access rd. intersection.</p>
<p style="text-align: right;">2</p>