

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 26, 27, 34 and 35

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1394-95)

-----  
Set post cor. of secs. 26, 27, 34 and 35, from which  
A Redwood 24" dia., bears N.3°W., 30 lks. dist.  
A Maple 8" dia., bears N.62°E., 52 lks. dist.  
A Maple 12" dia., bears S.57°E., 106 lks. dist.  
A Fir 60" dia., bears S.45°W., 23 lks. dist.

Oscar Thiel - June 20, 1942 (added 6/11/2012) - FB 117 Pg 28

-----  
All trees gone the cedar N.5°W., 30 lks.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; S. Bilow - Feb. 24, 1958 - C.S. File 49/59-13

-----  
Found - Two trees that I believe to be original BTs:  
24" Redwood, now 36" Cedar N.3°W., 19.8 ft., opened years ago, old face now rotted. I open lower scar which also shows rotted face. No scribing found, but I do find old axe marks. This BT checks for size and ring count.  
Also find base of large Fir stump that would check bearing and distance for orig. SW BT. Bark now gone from stump, no scribing found.  
Corner checks calls, North and East.

Set Brass cap at cor. mkd: County Surveyors Office  
T 22 S R 5 W  
S 27 | S 26  
S 34 | S 35  
1958

New BTs- 36" Cedar N.3°W., 19.8 ft. rescribed S27 T22S R5W CS BT  
14" W.Fir S.81°W. 38.4 ft scribed S34 T22S R5W CS BT  
18" R.Fir S.31°E. 62.0 ft scribed S35 T22S R5W CS BT  
4" Ewewood N.50°E. 9.8 ft scribed S26 T22S R5W CS BT

Fd. OK, DCSO, B.Rogers, Feb. 1965, C.S. File 53/101-86

Douglas Co. Surveyors Office - Gary L. Langlitz, Deputy - A.Vic Cangie, crew - June 10, 1976 - C.S. File 59/15-14

-----  
Found - A 1" I.P. protruding 14" out of ground, with 1958 DCSO brass cap.  
A 36" I.Cedar identified in 1958 as an orig. BT, bears N.3°W., 19.8 ft. with scribe marks visible in unhealed rescribe blaze.

(Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 500200

PRIMARY CORNER DESCRIPTION Sec. cor. for 26, 27, 34 and 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A 14" W.Fir, now a 20" rotten snag bears S.81°W., 38.4 ft. with scribing "22S R5W S34 CS BT" visible on an unhealed double blaze.  
An 18" now 24" D.Fir, alive and well healed, bears S.31°E., 62.0 ft.  
A 4" Yew marked by Byron, bearing N.50°E., 9.8 ft. is gone.  
We find no evidence of the orig. monument or any additional orig. BTs.  
New BTs -9" Yew bears N.64°W., 29.9 ft. scribed "T22S R5W CS BT" in a double blaze.  
A 15" Red Alder bears S.45°W., 10.4 ft. scribed "T22S R5W S34 CS BT" on a double blaze.

Robert Cook - For: Cambell-Global - 5/2019 - M175-60  
-----  
Found - 1958 DCS0 2½" brass cap up 15"  
10" yew N.64°W., 29.9 ft. scribes.  
48" D.Fir S.87°W., 70.8 ft. healed tag.