

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1396)

Set ¼ sec. post, from which
A Fir 4" dia., bears S.42°W., 44 lks. dist.
A Fir 40" dia., bears N.2°E., 79 lks. dist.

Gilbert A. Gardner - Sept. 1956 - C.S. File 42/179

Found - 32" Fir S.42°W., 29.0 ft. (Orig. BT)
50" Fir N.2°E., 52.0 ft. (Orig. BT)
Set 1" Iron pin.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - May 15, 1963 - C.S. file 49/59-38

Found - 1½" reinforcing rod stamped ¼ S23 26 on top.
36" Fir stump, S.42°W., 30.0 ft. (Rec. 29.0 ft.)
Sliver extending up from near center of stump shows old scribing "S" at approx. 4" dia.
Fir slab, only portion of large down Fir remaining standing, N.2°E., 52.0 ft. No marks found. Tree probably bark scribed and bark has been burned and is flaking off badly.
DID NOT SET A BRASS CAP.
New BTs -11" D.Fir N.30°W., 21.5 ft. mkd. ¼ S23 CS BT.
21" D.Fir S.3°E., 89.5 ft. mkd. ¼ S26 CS BT.

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 812 Surveyed Aug./Sept. 1973 (DCSO records Vol. 36 Page(s) 15065-66)

The ¼ sec. cor., perpetuated by Godfrey in 1963, monumented with an iron pipe, 1" dia., firmly set, protruding 4" above ground, from which the remains of the original bearing trees:
A root hole bears N.2°E., 79 lks. dist., with a down Fir alongside 46" dia., no marks visible.
A sawed and decayed Fir stump 36" dia., bears S.42°W., 44 lks. dist., with scribe marks 4S visible on remains of open blaze.
and bearing trees mkd. by Godfrey
A Fir 14" dia., bears N.30°W., 37 lks. dist. with healed blaze.
A Fir 23" dia., bears S.2°E., 135 lks. dist., with healed blaze.
At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd: (Cont. Next Page)

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 540300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 26

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

T 22 S R 5 W
1/4 $\frac{S\ 23}{S\ 26}$
1973

Fd. OK, Feb. 23, 1988, D. Peel, M 105-69