

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1392)

-----  
Set 1/4 sec. post, from which  
A Fir 30" dia., bears S.60°W., 360 lks. dist.  
A Fir 30" dia., bears S.80°E., 456 lks. dist.

Looked for, not found, DCSO, 1965, C.S. File 53/101-39

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 812 Surveyed Aug./Sept. 1973 (DCSO records Vol. 36 Page(s) 15063-64)

-----  
Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

1/4  
S 23 | S 24  
T 22 S R 5 W  
1973

from which

A Fir 10" dia., bears S.47°E., 36 lks. dist. mkd. 1/4 S24 BT  
A Fir 10" dia., bears N.33°W., 66 1/2 lks. dist. mkd. 1/4 S23 BT.

Fd. OK, Feb. 23, 1988, D.Peel, M 105-69