

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 620200

PRIMARY CORNER DESCRIPTION W. 1/16 cor. between Secs. 25 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Stephen Flause, Karen Mosley, crew - May 13, 1981 - C.S. File 61/24

-----  
Found - A 5/8" Iron rod as set by Haines (M 80-54), is firmly set and protrudes 9" from the ground.

A 40" D.Fir now a Fir stump, 40" dia., and 30" tall, with a metal weather protection cap, bears S.51°E., 62.4 ft. and scribing "BT" visible on a partially healed single blaze.

A 14" D.Fir now a fallen 14" DBH D.Fir bears S.60°W., 32.4 ft. with the scribing "1/16 S36 BT" visible on a partially healed single blaze.

Haines monument is accepted as found.

New BTs -A double trunk Maple with an average DBH of 30", bears S.20½°W., 61.2 ft. and is bark scribed "W 1/16 S36 CS BT"

A 32" DBH D.Fir bears S.71½°W., 36.3 ft. and is scribed "W 1/16 S36 CS BT" on a double blaze.

BT tags are placed on new BTs and the fallen 14" Fir.

DCSO-GIS Corner visitation - 1/9/2006 - Typed: 1/19/2011 - C.S. File 67/33-1

-----  
Monument - 5/8" IR

Comment - (Needs) rehab 2 stumps & 1 snag.