

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1391-92)

Set ¼ sec. post, from which
A B.Oak 14" dia., bears N.30°W., 83 lks. dist.
A Fir 24" dia., bears S.46°W., 141 lks. dist.

Looked for, not found, DCSO, C.S. File 53/101-19

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 812 Surveyed Aug./Sept. 1973 (DCSO records Vol. 36 Page(s) 15062-63)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
1/4 $\frac{S\ 24}{S\ 25}$
T 22 S R 5 W
1973

from which
A Fir 13" dia., bears N.66½°E., 81½ lks. dist. mkd. ¼ S24 BT.
A Fir 9" dia., bears S.85°E., 93½ lks. dist. mkd. ¼ S25 BT

Found OK by David Brown, Jan. 1998 - M 124-70

Harvey Christensen - For: Roseburg Resources - 6/2005 M148-13

Found - 1973 2.5" BLM BC, 0.4' above ground.
New - 8" D.Fir S.80°E. 24.8 ft blazed & scribed "¼ S25 BT"
7" D.Fir S.45°W. 21.1 ft blazed & scribed "¼ S25 BT"
7" D.Fir N.72°E. 33.9 ft blazed & scribed "¼ S25 BT"
16" D.Fir N.28°W. 64.3 ft blazed & scribed "¼ S25 BT"
Found - 15" D.Fir N.66.5°E., 53.8 ft healed face, 5" high stump.
12" D.Fir S.85°E., 61.7 ft healed face, 5" high stump.
Note - Corner is in open area near reprod, 4 fence posts located around corner.

DCSO-GIS Corner visitation - 1/9/2006 - Typed: 1/19/2011 - C.S. File 67/33-1

Monument - 3" BC. Comment - OK, 4 live BTs