

TOWNSHIP 22 RANGE 05 POINT IDENTIFIER # 660300

PRIMARY CORNER DESCRIPTION E. 1/16 Cor. betw. Secs. 24 & 25

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Daniel Berry and Charles Akin Cadastral Surveyors, under Group # 812 Surveyed Aug./Sept. 1973 (DCSO records Vol. 36 Page(s) 15062)

Point for the E 1/16 sec. cor. of secs. 24 and 25.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground,
with brass cap mkd: E 1/16 $\frac{S\ 24}{S\ 25}$
1973

from which

A Fir 13" dia., bears N.31°W., 44 lks. dist. mkd. E 1/16
S24 BT.

A Fir 9" dia., bears S.30°E., 109½ lks. dist. mkd. E 1/16
S25 BT.

Douglas Co. Surveyors Office - Randall Smith and Stephen
Flause, crew - Feb. 7, 1992 - C.S. File 64/23-7

Found - A 3¼" dia. 1973 brass cap/iron pipe surrounded by a
12 ft. x (?) ft. mass of concrete. (BC/IP had
been hit by farm equipment. Flanges held. Mr.
Heise plumbed BC/IP and surrounded BC/IP with
concrete for protection. No collaborating
evidence from 1973 BLM.

BTs from 1973 BLM survey have been cut down. No
evidence remains.

New BTs -A double trunked I.Cedar double blazed and scribed
"E 1/16 S24 CS BT" on 15" dia. South trunk, bears
N.75°E., 266.1 ft. to center of root crown.

12" dia. D.Fir, double blazed and scribed "E 1/16
S25 CS BT" bears S.9¼°E., 104.1 ft.

9" dia. Apple tree, not blazed or scribed, bears
S.28½°W., 45.2 ft.

DCSO-GIS Corner visitation - 1/9/2006 - Typed: 1/19/2011 -
C.S. File 67/33-1

Monument - 3" BC set in concrete.

Comment - OK; 3 live BTs.