

PRIMARY CORNER DESCRIPTION NW Cor. Ensley DLC #44

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy,
dated Sept. 1856

Set post NW cor., from which
 A Fir 18" dia., bears N.60°E., 47 lks.
 An Oak 18" dia., bears S.70°W., 57 lks.

F.C. Frear, Deputy Co. Surveyor - Wit: J.W. Harness; Earl
Frier - Dec. 1917 - C.S. File 1/4; Vol. 3 Page 3; and M 1-6

Renew from old BTs.
Set in a 1" x 30" Iron pipe, from which
 An 18" Fir bears S.46°E., 0.395 chs. dist.
 A 36" Fir bears N.59¼°E., 0.470 chs. dist.
 A 24" Oak bears S.79°W., 0.54 chs. dist.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 12/6/1999 - C.S. File 66/13-5

Found - 1" I.D. iron pipe protrudes 7" above ground. 1917
East-North fence cor. is 5.5 ft. south of IP
Orig. SW BT not found
18" now 36" dia., down D.Fir, large root hole agrees
 with rec. N.60°E., 31.0 ft. OBT.
18" now 22" dia., 3½" high D.Fir stump with a
 partially healed blaze illegible scribing visible
 bears S.46°E., 26.1 ft. 1917
New BTs- 12" dia., W.Oak double blazed & scribed "NW DLC 44
 CS BT" bears N.47½°E., 24.4 ft.
 6" dia., W.Oak double blazed & scribed "NW DLC 44
 CS BT" bears N.65°W., 13.9 ft.
 12" dia., Cedar double blazed & scribed "NW DLC 44
 CS BT" bears S.34°W., 39.2 ft.
Corner lies 15 ft. north of a NE running ravine.

1