

PRIMARY CORNER DESCRIPTION SE Cor. Ensley DLC #44

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856</p> <p>-----</p> <p>Set post SE cor., from which An Oak 6" dia., bears N.6°E., 250 lks. A Fir 15" dia., bears S.80°W., 150 lks.</p>
<p>Wilford N. Haines - For: Ray Heaton - July 15, 1965 - M 30-16</p> <p>-----</p> <p>Found - Rock mkd. with 44. Orig. Fir BT, now snag, S.80°W., 150 lks. Set "T" Iron by rock.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 12/1/1999 - C.S. File 66/13-1</p> <p>-----</p> <p>Found - T-iron protrudes 3" above ground along northerly edge of firmly set stone 5"x5"x8" long marked on top "44", 3" below ground. Source of stone unknown, T-iron from M 30-16, 1965 15" now 38" dia., 3 ft. high rotted D.Fir stump signs of old search, no scribing visible, bears S.82°W., 66.0 ft. (orig. rec. S.80°W. 99 ft.) OBT Note: Distance error? stump opened further no scribing found. Orig. NE BT not found. We protect position of found monuments. New BTs- 14" dia., Maple double blazed & scribed "DLC 44 CS BT" bears N.74°E., 13.8 ft. 9" dia., D.Fir double blazed & scribed "DLC 44 CS BT" bears N.39½°E., 9.0 ft. Looked for a Fir at orig. rec. S.80°W., 150 lks., no evidence found.</p>
<p> </p>