

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Section 21 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1455)

Set ¼ sec. post, from which
A Fir 8" dia., bears S.25°E., 25 lks. dist.
A Dogwood 12" dia., bears S.10°W., 15 lks. dist.

GLO survey by Nicklin, Contract #664, dated May 23, 1896 "After diligent search, I could find no trace of the ¼ sec. cor." (DCSO records, Vol. 4 Page 1483)

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #1073, surveyed Aug/Sept. 1981 (DCSO records Vol. 44 Page(s) 17029)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an alu. post, 28" long, 2 1/2" dia., 24" in the ground, with alum. cap mkd:
T 22 S R 6 W
| 1/4 S 21
1981

from which
A Fir 10" dia., bears N.60°E., 33½ lks. mkd. ¼ S21 BT.
A Hemlock 11" dia., bears S.80¼°E., 6½ lks. mkd. ¼ S21 BT.

BLM dependent resurvey by Jeffrey O. Covington, Cadastral Surveyor, under Group No. 2875, surveyed Aug. 2017/Feb. 2019- (DCSO records Vol. 59 Page 23647)

The ¼ sec. cor. of sec. 21 only, monumented with an aluminum post, 2½" dia., firmly set, projecting 10" above ground, with an aluminum cap (properly) mkd.
from which the remains of the BTs mkd. by Jelley in 1981
A fir, 18" dia., bears N.60°E., 22.1 ft., with a healed blaze.
A hemlock snag, 15" dia., bears S.80¼°E., 4.3 ft., with a healed blaze.
and a new bearing tree
A hemlock, 16" dia., bears S.65¾°E., 12.4 ft. mkd ¼ S21 BT
Each new BT has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center & each corner established or remonumented has a magnet deposited in a white plastic case at the base of the stainless steel post. Alum. Angle iron driven alongside each monument.