

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1442)

Set post cor. of secs. 10, 11, 14, and 15, from which

A B.Oak 15" dia., bears S.47°W., 175 lks. dist.

A B.Oak 30" dia., bears N.30°E., 267 lks. dist.

Raised mound with trench as per instructions.

Ben B. Irving, Co. Surveyor - Wit: W.S. Crear; Geo. Montgomery - Dec. 1927/Jan. 1928 - C.S. File 22/25 and Vol. 3 Page 284

O.B.T.s as called for in original field notes. One with scribe marks well preserved and the other so badly charred that no scribe marks remained but position checked.

Set 2" x 36" Iron pipe for corner driven 30" in ground.

A 36" B.Oak bears N.15°E., 38 lks. on slope of 21°41', scribed T22S R6W S11 CS BT.

A 24" W.Oak bears S.65½°W., 143 lks. on slope of 19°10', scribed T22S R6W S15 CS BT.

A 30" W.Oak bears S.21°W., 202 lks. on slope of 18°30', scribed T22S R6W S15 CS BT.

O.F. Thiel - For: Vernon Goodrich - Aug. 1944 - Field Book 118 Page 21

NE Cor. of sec. 15, 2½" Iron pipe.

Fd. OK, March 1960, W.Haines, M 18-32
FD IP & 3 BTs 9/1961 - DCSO Milo Godfrey C.S. File 49/143-78

BLM resurvey by Donald Beck, Cadastral Surveyor, under Group #517, surveyed Aug/Sept. 1963 (DCSO records Vol. 32 Page(s) 13447-48)

The Sec. cor., perpetuated and recorded by Irving in 1928, monumented with a water pipe, 2½" dia., protruding 8" above ground, from which the remains of the origin NE BT:

A sawed Oak stump 43" dia., bears N.30°E., 270 lks. dist., 267 lks. to the face, S in negative on overgrowth lying alongside the stump. (Rec. dist. 267 lks.)

and bearing trees by Irving in 1928

An Oak 36" dia., bears N.14 3/4°E., 353 lks. dist., mkd. with a healed blaze.

An Oak 35" dia., bears S.65¼°W., 138 lks. dist. mkd. S15 T22 R6 CS on partially healed blaze.

At the corner point

(Cont. Next Page)

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 500500

PRIMARY CORNER DESCRIPTION Sec. Cor. for 10, 11, 14 and 15

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set an iron post, 28" long, 2 1/2" dia., 22" in the ground,
with brass cap mkd:

T 22 S R 6 W
S 10 | S 11
S 15 | S 14
1963

No other suitable bearing trees available within limits.
Reset water pipe alongside the iron post.

Fd. OK, March 1990, J. Branch, M 109-74

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 10/1/2001 - C.S. File 66/29-15

Found - 1963 BLM brass cap iron pipe, protrudes 4" above
ground.
1928 2" iron pipe protrudes 15" above ground along
north edge of BLM BC/IP.
24" now 38" dia., W.Oak with a previously opened
unhealed, rotted blaze, faint scribing visible "S
T 22 CS" bears S.65¼°W., 91.1 ft. (1928)
36" now 42" dia., B.Oak with a fully healed high
single blaze & Haines washer, bears N.14¾°E.,
233.0 ft. (1928)
New - 6" dia., D.Fir double blazed & scribed "X S10 CS BT"
bears N.34°W., 6.6 ft.
6" dia., D.Fir double blazed & scribed "X S14 CS BT"
bears S.46°E., 12.7 ft.
Compass Decl. 17½°E.

Fd. Ok by D. Edwards, 7/20/2007 - M153-62