

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 35 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1430)

Set ¼ sec. post C.C., from which
A Fir 30" dia., bears N.33°W., 17 lks. dist.
A Fir 5" dia., bears N.27°E., 24 lks. dist.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12626)

Point for the ¼ sec. cor. of sec. 35, T22S R6W at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long 1" dia., 27" in the ground, with brass cap mkd: ¼ S 35
1943

from which
A Fir 50" dia., bears N.48°E., 88 lks. dist., mkd. ¼ S35 BT.
A Fir 14" dia., bears N.76°W., 66 lks. dist., mkd. ¼ S35 BT.

BLM corrective and dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Robert H. Browning, Surveying Technician, under Group #1803 surveyed May/Nov.. 1996 - (DCSO records Vol. 52 Page(s) 19958-9)

The ¼ sec. cor. of sec. 35 only, T.22S., R.6W., monumented with an iron post, 1" diam., firmly set, projecting 10" above ground, with brass cap mkd. ¼ S 35
1943

from which the remains of a BT mkd. by Gould, Gawron, & Eggen
A sawed fir stump, size indeterminate, bears N.40½°E., 88 lks., no marks visible. (Record N.48°E.)
and new bearing trees
A fir, 7" diam., bears N.40½°E., 16 lks., mkd. ¼ S35 BT.
A fir, 15" diam., bears N.26 ¾° W., 7 lks. mkd. ¼ S35 BT
This corner was set concurrently with the corners of the Fifth Standard Parallel South, making it a corner of minimum control, not a closing corner.