

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Section 12

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

<p>O.F. Thiel - For: Ray B. Ritchey - 1906 - C.S. File 64/48 Page 7</p> <p>-----</p> <p>Cedar post. At center of 12 stone 5 x 8 x 12 .80 S of stone C.S. marked Wh. Fir 8" S.53°E., 12; same Cedar bears N.73°E., 1.62 (now 15") from C.S. stone.</p>
<p>O.F. Thiel - For: Eddie G. Tanner - April 24, 1950 - Field Book 20 Page 10</p> <p>-----</p> <p>Stone, center of sec 12 T22S R6W.</p>
<p>Wilford N. Haines - For E. Tanner - Feb. 1, 1955 - M 10-39; Field Book H-237</p> <p>-----</p> <p>Rock with X on top. 40" W.Fir S.50°E., 6.7 ft. dist.</p>
<p>Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - (no date) - C.S. File 42/125</p> <p>-----</p> <p>(Information telephoned in to office) BT dead or dying, endangering house. Has to be cut. I found rock with "X" on top. W.Fir (now 48" dia.) S.50°E., 6.7 ft. showing scar. Tree dying. Dist. measured from face of tree. This was apparently set for center ¼ Sec. 12, T22S R6W. From talking to people, think cor. was probably set by Thiel. Has been used by Haines. (See M 10-39) Can not find record of cor. being set. This job only reference I find of this cor. Did Not Renew. Told people to go ahead and cut tree, but be careful not to disturb rock.</p>
<p>James Branch, surveyed for McArthur &amp; Assoc. Inc. Feb. 1999 M129-33</p> <p>-----</p> <p>Set - 5/8" x 30" rebar w/yellow plastic cap marked "BRANCH ENGINEERING", 0.4 ft. below ground surface in gravel driveway.</p> <p>From which:</p> <ul style="list-style-type: none"><li>A found 5/8" iron rod lying 4 feet south of a fence corner bears N.86°05'26"W., 103.58 feet.</li><li>A 5/8" iron rod with red plastic cap marked "REF. MON. BRANCH ENG." lying 23 ft. east of a 12" pine tree, bears N.19°35'25"E., 57.01 ft.</li></ul> <p>Cont. next page</p>

TOWNSHIP 22 RANGE 06 POINT IDENTIFIER # 640540

PRIMARY CORNER DESCRIPTION CENTER 1/4 SECTION 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From which continued:  
A 5/8" iron rod with red plastic cap marked "REF. MON. BRANCH ENG." lying 2 ft. southwest of the corner of a cyclone fence, bears N.74°01'59"E., 14.88 ft.  
A 5/8" iron rod with red plastic cap marked "REF. MON. BRANCH ENG." lying 5 ft. west of the SE corner of a well house, bears S.11°03'44"W., 18.11 ft.  
Note - No bearing trees available except ornamental plantings.

Fd. 5/8" rebar with cap by D.Edwards, 4/2009 - M159-35