

PRIMARY CORNER DESCRIPTION Int. Cor. Wm. Hancock DLC #45

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856</p> <p>-----</p> <p>At the interior corner on right bank of Elk Creek in Sec. 21, Set post, from which</p> <p> An Oak 24" dia., bears S.78°W., 315 lks.</p> <p> An Alder 12" dia., bears S.47°W., 55 lks.</p>
<p>Floyd Cole, Deputy - Wit: S. Brown; W. Frost - July 5, 1913 -Vol. 2 Pg. 253-4; Vol. 3 Pg. 87 and Field Book 39 Pg. 4</p> <p>-----</p> <p>Reestablished the interior "L" cor. of Cl. 45, from which</p> <p> A R.Fir 24" dia., bears N.80°W., 6 ft. dist.</p> <p> An Oak 12" dia., bears S.66°E., 3 ft. dist.</p>
<p>J.W. Cole, Deputy - Wit: Edward Hancock; Leslie Hancock - Feb. 1921 - Field Book 50 Page 12</p> <p>-----</p> <p>Located this corner from testimony given by Ed Hancock as to the position of the witness trees, as this put me on a line run due North of the SE corner of the Claim with but 16.5 ft. over measure from distance called for in field notes, also due West of NE inter "L" corner. I consider this as all of the evidence as possible to get and set a 4" x 4" x 36" Post, also 2" Iron pipe for corner., from which</p> <p> An Oak 20" dia., bears N.45°W., 31.3 ft. dist.</p> <p> An Oak 15" dia., bears N.75°15'E., 68.0 ft. dist.</p> <p>F.J. Coles cor. bears N.75°40'E., 65.0 ft.</p>
<p>Searched for twice - not found - Dec. 1959</p>
<p>BLM dependent resurvey by Bryan S. Seibold, Cadastral Surveyor, under Group #1797, surveyed April/June 1996 - (DCSO records Vol. 52 Page(s) 20166)</p> <p>-----</p> <p>Point for the interior "L" corner of DLC No. 45, at proportionate distance, determined by the Grant Boundary Method between the original SW. cor. of Donation Land Claim No. 45 and the restored NE. cor. of Donation Land Claim No. 45, there is no remaining evidence of the original corner; <u>no permanent monument set.</u></p>
<p>continued next page</p>

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 045050

PRIMARY CORNER DESCRIPTION Int. Cor. Wm. Hancock DLC #45

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor, under Group #2034, surveyed 2002/2003 (DCSO rec. Vol. 54 pg(s) 21046)

Beginning at the interior "L" cor. of Donation Land Claim No. 45, as reestablished and described by Bryan S. Seibold, Cadastral Surveyor in 1996, under Oregon Group No. 1797, accepted June 23, 1998. Seibold did not monument this position.

This corner point was not corrected during this corrective resurvey even though it was reestablished at proportionate position by Seibold in 1996. The reason for this is outlined in a report in the survey group file for Gp. 2034, Oregon. Cor. is located on the right bank of Elk Creek, just above the Mean High Water Mark.