

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 17 and 20

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1510)</p> <p>-----</p> <p>Set ¼ sec. post, from which A B.Oak 5" dia., bears S.5°W., 64 lks. dist. A W.Oak 4" dia., bears N.10°E., 159 lks. dist.</p>
<p>A. Boyer - August 1913 - Vol 2 Page 254 & Field book 34 Pg 4</p> <p>-----</p> <p>W. Oak 8", N.40 3/4°E., 385 3/4 lks. W.Oak 6" S.48°W., 220 lks.</p>
<p>Wilford N. Haines - For: Yoncalla Lumber Co. - March 1961 - M 22-1</p> <p>-----</p> <p>Found two Oak BTs. Set 1" x 1" x 36" T. Iron.</p>
<p>Charles W. Guile - For: John Winslow - April 1980 - M 82-72</p> <p>-----</p> <p>Found - 72" triple Oak, N.40°43'43"E., 253.95 ft. (N.40°45'E., 253.3 ft., 1931 Re-estab data) 30' Oak, S.47°58'43"W., 145.6 ft. S.48°W., 145.2 ft., 1931 Re-estab data) Set - 5/8" iron rod.</p>
<p>Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 7/29/1998 - C.S. File 66/4-2</p> <p>-----</p> <p>Found - 5/8" iron rod protruding 2" ground. (1980) Haines "T" iron not seen. No OBTs found. 8" now 72" dia., triple trunked W.Oak, no blazes or scribing visible, 36" dia., southerly trunk bears N.40¾°E., 254.0 ft. (Agrees well with record) 1913 6" now 33" dia., W.Oak with a fully healed single blaze, bears S.48°W., 145.2 ft. (Agrees well with record) 1913 New BOs- 5/8" iron rod found 2" below ground at fence corner with fence lines running east & north, I.R. is at south edge of 8"x6" wooden corner post, we add BT tag to corner post, I.R. bears East, 133.3 ft. 14" dia., W.Oak, double blazed and scribed "¼ S20 CS BT" bears S.3¾°E., 250.9 ft.</p>
<p>Fd. Ok by K. DeGroot, 12/2006 - M146-51</p>