

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1523)

Set ¼ sec. post, from which
A Fir 24" dia., bears N.10°E., 46 lks. dist.
A Fir 48" dia., bears S.45°E., 75 lks. dist.

GLO survey by Carl Nicklin, under joint contract #664 dated May 23, 1896 (DCSO records, Vol. 4 Page 1545)

"After diligent search, I am unable to find the ¼ Sec. Cor."

Wilford N. Haines - For: Woolley Logging Co. - Sept. 1960
M 11=72

Found Byar's BTs, both down.
Set 1" x 1" x 36" T iron.
Scribe - 40" Fir N.42°W., 22.3 ft.
20" Fir S.09°W., 12.2 ft.

Tony Hostetter - For: Seneca Jones Timber Co. - July 2003 -
M142-68

Found - 1" T-post w/brass cap & both BTs as described by Haines in 1960 (M11-72)
New BTs- 8" Fir scribed "S3 ¼ BT", bears N.06°08'E., 33.0 ft. to spike.
16" Cedar, scribed "S3 ¼ BT" bears N.53°40'E., 22.8 ft. to spike.

Ronald L. Rice, Ward NW - For: Seneca Jones Timber Co. -
12/2003 - M 143-57

Condition report
Found - 1" Haines "T" iron
48" D.Fir bears N.42°W 23.7', bark scribed
36" D.Fir bears S.9°W., 12.2', bark scribed
8" D.Fir bears N.6¼°E 33.0', to spike in face open face, scribing visible.
16" Cedar bears N.53¾°E., 22.8', to spike in face open face, scribing visible.
Note - All corners have a 5½" galvanized steel post adjacent to the cor. monument. Corner accessories have red painted band & face plus yellow BT tag where appropriate.

continued next page

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 3 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

David Edwards - For: Seneca Jones Tmbr Co. - 6/2020 - c.s.
File 65/107-001

Found as per M143-57 except that a large tree has fallen and badly bent the T-Iron

New - Haines' T-Iron fd in poor condition and replaced with a 5/8"x30" steel rebar with RED plastic cap stamped:
D.A. EDWARDS-LS 2339

6 FT. POST S.89°30'E., 2 ft.