

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor under contract # 152 survey dated June 3, 1871 (DCSO records Vol. 4 Page(s) 1517-18)

-
- Set post cor. to secs. 14, 15, 22, and 23, from which
- A Fir 10" dia., bears N.84°E., 34 lks. dist.
 - A Fir 12" dia., bears S.2°E., 12 lks. dist.
 - A Fir 8" dia., bears S.15°W., 37 lks. dist.
 - A W.Oak 8" dia., bears N.58°W., 35 lks. dist.

BLM resurvey by John M. Jelley and Donald Beck, Cadastral Surveyors, under Group #590, surveyed July/Aug. 1965 (DCSO records Vol. 33 Page(s) 13952-53)

Point for the sec. cor., at proportionate distance; there is no remaining evidence of the original corner. The line bet. secs. 15 and 22 was completed by Byars in 1871. Byars made no mention of the original ¼ sec. cor. and witness point of secs. 15 and 22 established by Gordon and Gardner in 1855, and established his own ¼ sec. cor. for secs. 15 and 22. There is no remaining evidence of the Byars ¼ sec. cor., but the original ¼ sec. cor. and witness point have been recovered and remonumented by the Douglas Co. Surveyor. The position of this sec. cor. is based on the original cor. of secs. 15, 16, 21 and 22, as control to the West and Byar's returns of the line bet. secs. 15 and 22, because no correlation was ever established bet. the orig. ¼ sec. cor. or the witness point and the cor. of secs. 14, 15, 22 and 23. Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 22 S R 7 W
S 15 | S 14
S 22 | S 23
1965

from which

- A W.Fir 25" dia., bears N.22½°E., 399 lks. dist. mkd. T22S R7W S14 BT.
- A Fir 12" dia., bears S.83 3/4°E., 283 lks. dist., mkd. T22S R7W S23 BT.
- A Fir 11" dia., bears S.81¼°W., 383 lks. dist. mkd. T22S R7W S22 BT.
- A W.Oak 12" dia., bears N.74°W., 221 lks. dist. mkd. T22S R7W S15 BT.

John E. Hollingsworth - For: Oregon State Parks and Recreation Division - Jan. 21, 1987 - C.S. File 63/62 and M 104-77

(Cont. Next Page)

TOWNSHIP 22 RANGE 07 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

CONDITION REPORT ONLY

Found - 1965 BLM brass cap firmly set and 0.3 ft. above ground.

34" W.Fir snag N.22½°E., 263.3 ft. with rotted face in open blaze.

31" Fir N.24½°E., 279.2 ft., scribes visible "T22S R7W S14 BT" (no record)

20" Fir S.83 3/4°E., 186.8 ft. with healed blaze scar.

34" Fir S.81¼°W., 252.8 ft. with healed blaze scar.

20" Oak N.74°W., 145.9 ft. with healed blaze scar.

Set orange Carsonite post with decal marked "Property Boundary-State Park Land Behind This Sign", 2.0 ft. NW.

Elk Creek Tunnel Forest State Park. Corner falls in a field 116.2 ft. East of a N-S fence and 306.9 ft. South of an E-W fence. Bearings and distances by hand compass and steel tape.

Fd. OK, March 1998 by G. Riley - M 128-33

Fd. Ok, July 2005 by D. Edwards - 2005-0070