

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 043070

PRIMARY CORNER DESCRIPTION SW Cor. Wm. Helbert DLC #43

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<p>Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated Sept. 1856</p> <p>-----</p> <p>Set SW cor. Claim 43, from which A Chittim 6" dia., bears West, 19 lks. An Oak 12" dia., bears N.1°E., 189 lks.</p>
<p>H. L. Eppstein, Co. Surveyor - Bert Lane and N.E. Richardson, witnesses - June 1934 - County Road records, Sheet 3 of 10, Thomas Road #118 (and "old" corner book, Page 25)</p> <p>-----</p> <p>This cor. was a plow, but due to the location would be destroyed. So I set from the corner, a 3/4" x 16" round Iron bar, North, 30 ft. and a 1/4" x 1 1/2" x 16" iron bar, South, 40 ft., from which The old BT is in evidence, 12" Oak N.1°E., 189 lks. I marked: A 24" W.Oak N.31°W., 359.3 ft. as new BT, "Cl 43 CS BT" (Sta. 70+46.5 is 2.5 ft. South of SW Cor. Cl. 43)</p>
<p>Douglas County Surveyors Office - Milo E. Godfrey, Deputy - C.S. File 52/14-90</p> <p>-----</p> <p>Corner searched for, not found.</p>
<p>Looked for, not found, Oct. 11, 1988, DCSO, C.S. File 62/59-4</p>
<p>Mark Smalley - For: Roseburg Resources - 12/2000 - M 132-59</p> <p>-----</p> <p>Set - 5/8" x 48" iron rod & alum. cap mkd: "LS 2354 2000 WC 50' ↑" in cut slope of road. 6" Alder S.4°W., 8.2 ft. "SW DLC 43 WC BT" 7" Alder N.84°W., 16.6 ft. "WC SW DLC 43 BT" 6" Fir N.68°E., 19.4 ft. "WC SW DLC 43 BT" Plastic cap on iron rod in fence corner bears N.2°08'13"W., 77.12 ft. mkd: "LS 1076". M 109-6</p>
<p>Fd 5/8" IR W/alum cap (WC) as per M132-59 - N Hibbs - 3/2023 - M182-20</p>
<p> </p>