

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 246300

PRIMARY CORNER DESCRIPTION S. M.C. So. bdy. Sec. 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Dec. 27, 1962 - C.S. File 52/14-131

Corner searched for, not found.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records Vol. 34 Page(s) 14119)

Point for the meander corner bet. secs. 20 and 29, at record bearing and distance; there is no remaining evidence of the original corner. No permanent monument established.