

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1604)

Set Fir post for ¼ sec. cor., from which
A Fir 16" dia., bears N.1°E., 155 lks. dist.
A Fir 24" dia., bears S.1°W., 191 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Crew, Milo Godfrey; A. Bilow - April 16, 1958 - C.S. File 49/77

Found - Orig. 24" now 38" Fir S.1°W., 26.1 ft. Old bark scribing "¼S".

Orig. NE BT, not found.

Set Brass cap at cor. mkd: County Surveyors Office
T 22 S R 8 W
¼ S5|S4
1958

New BTs -26" R.Fir bears S.83°W., 10.0 ft. scribed ¼ S5 CS BT
26" R.Fir bears S.5°E., 68.1 ft. scribed ¼ S4 CS BT.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Mike Stone & Vernon "Ray" Tracy, crew - Dec. 1962 - C.S. File 52/14-47

Found - Brass cap set by DCSO in 1958.
Fir S.83°W., 10.0 ft., alive and in good condition, scribing visible.
Fir stump S.5°E., 68.1 ft. "BT" still on stump, rest of scribing gone with log.

New BT - 16" D.Fir N.25°E., 29.9 ft. mkd. ¼ S4 CS BT.

BLM resurvey by Floyd A. Brooks and James E. Jelley, Cadastral Surveyors, under Group #'s 514 and 350, surveyed June 1963/March 1965 (DCSO records Vol. 33 Page(s) 13699-700)

The ¼ sec. cor., perpetuated and recorded by Byron in 1958, monumented with an iron post 1½" dia., 10" above ground, firmly set, with 1958 brass cap from which the remaining original bearing tree,

A sawed Fir stump 26" dia. bears S.1°W., 191 lks. dist. with no marks remaining.

bearing trees mkd. by Byron:

A sawed Fir stump 26" dia., bears S.5°E., 103 lks. dist. with scribe marks BT visible on unhealed blaze.

A Fir 26" dia., bears S.83°W., 15 lks. dist. with scribe marks ¼ S5 BT visible on unhealed blaze.

and a bearing tree mkd. by Godfrey in 1962,

(Cont. Next Page)

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 300640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 4 and 5

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 16" dia., bears N.25°E., 47 lks. dist. with scribe marks ¼ S4 CS BT visible on unhealed blaze.
ADD the marks B L M 1963 to brass cap.

FD. OK - Les Roberts - M 124-44 & CS 65/12-5 A&B - 2-10-97

BLM remonumentation by Aaron M Graham, Cadastral Surveyor and Michael Jones Surveying Technician under Group #2199 surveyed April 2008/April 2009 - (DCSO rec. Vol. 56 Pages 21943-4)

The ¼ sec. cor. of secs. 4 and 5, perpetuated from original evidence no longer in existence by Byron in 1958; monumented with an iron post, 1½" dia., firmly set, projecting 24" above ground, with a brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Byron in 1958 and reported by Brooks and Jelley in 1963-65

A fir stump, size indeterminate, bears S.5°E., 68.0 ft., no marks visible.

A fir, 41" dia., bears S.83°W., 9.9 ft., with a healed blaze.

and a bearing tree mkd by Godfrey in 1962-63 and reported by Brooks and Jelley in 1963-65

A fir, 39" dia., bears N.25°E., 31.0 ft., with a healed blaze.