

TOWNSHIP 22 RANGE 08 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 11 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W.H. Byars, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 4 Page(s) 1596)

Set Fir post for ¼ sec. cor., from which
A Fir 50" dia., bears N.87°E., 18 lks. dist.
A Fir 48" dia., bears S.87°W., 75 lks. dist.

Douglas County Surveyors Office - Milo E. Godfrey, Deputy -
C.S. File 52/14-134 - Nov. 13, 1962

Corner searched for, not found.

BLM resurvey by Floyd Brooks and Peter Peterson, Cadastral Surveyors - under Group #'s 595 and 657 - surveyed Aug. 1965/Dec. 1967 - (DCSO records Vol. 34 Page(s) 14109)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼
S 11 | S 12
T 22 S R 8 W
1967

from which

A Fir 8" dia., bears S.49°E., 72 lks. dist. mkd. ¼ S12 BT
A Fir 4" dia., bears N.25°W., 34 lks. dist. mkd. ¼ S11 BT

Fd. OK, July 1985, by L. Roberts, M 90-74

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor and Michael O. Jones Surveying Technician, under Group #2199, surveyed April 2008/April 2009 - (DCSO rec. Vol. 56 Pg 21939)

The ¼ sec. cor. of secs. 11 and 12, reestablished by Brooks and Peterson in 1965-67; monumented with an iron post, 2½" dia., firmly set, projecting 5" above ground, with a brass cap (properly) mkd.

from which BTs mkd. by Brooks and Peterson in 1965-67

A fir, 17" dia., bears S.49°E., 47.5 ft., no marks visible, with BT tag.
A fir, 15" dia., bears N.25°W., 22.4 ft., no marks visible, with BT tag.