

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 28 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16052)

Point for the ¼ sec. cor. of sec. 28 only, at proportionate distance.

Set an iron post, 28" long, 2½" dia., 20" in the ground, with brass cap mkd:

T 22 S R 9 W

¼ S 28

1975

from which

A Fir 12" dia., bears N.4°E., 21 lks. dist. mkd. ¼ S28 BT.

A Fir 14" dia., bears N.36°W., 34 lks. dist. mkd. ¼ S28 BT

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17922-23)

Point for the ¼ sec. cor. of sec. 28 only, at proportionate dist., on the S. bdy. of sec. 28.

From this point, the ¼ sec. cor. of sec. 28 only. erroneously established by Wofford, etal, 1973-79, bears S.76°57'W., 0.18 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post, destroy the marks on NE. bearing tree, and at the true corner point.

RESET the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W

¼ S 28

1984

from which a bearing tree mkd. by Wofford, etal,

A Fir 15" dia., bears N.59½°W., 43½ lks. dist. with healed blaze.

and a new bearing tree

A Fir 15" dia., bears N.6 3/4°E., 35 lks. dist. mkd. ¼ S28 BT.