

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. Section 10 only

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Elmer O. Worrick, Deputy Surveyor, under Contract #632, dated April 28, 1894 - (DCSO records Vol. 4 Page(s) 1662-63)

Set Maple post 4½ ft. long, 4" sq., 24" in ground on hillside sloping W. for ¼ sec. corner, mkd. ¼ S on W. face, from which
A Maple 10" dia., bears N.34°E., 18 lks. dist. mkd. ¼ S BT
A Maple 12" dia., bears N.58°W., 31 lks. dist. mkd. ¼ S BT

BLM resurvey by Joel E. Robb, Cadastral Surveyor, under Group #1367, surveyed Apr/June 1987 - (DCSO records Vol. 45 Page(s) 18426-27)

Point for the ¼ sec. cor. of sec. 10 at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:

T 22 S R 9 W

¼

S 10

1987

from which

A Fir 18" dia., bears N.53°E., 52 lks. dist. mkd. X BT.

A Fir 16" dia., bears S.79°E., 16 lks. dist. mkd. ¼ S10 BT.

Deposit white "DEEP-1" magnetic marker at base of iron post.

Fd. & used on Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19883)