

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 27 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16043)

-----  
Point for the ¼ sec. cor. of sec. 27 only, at midpoint longitudinally on the S. bdy. of sec. 27.  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:  
T 22 S R 9 W  
¼ S 27  
1974

from which  
A Fir 9" dia., bears N.67°E., 35 lks. dist. mkd. ¼ S27 BT.  
A Fir 10" dia., bears N.37½°W., 16 lks. dist. mkd. ¼ S27 BT.

BLM Corrective Dependent resurvey by Stephen J. Malloy and John P. Farnsworth, Cadastral Surveyors, under Group #'s 1125 and 1226, surveyed Nov./Dec. 1982 - (DCSO records Vol. 47 Page(s) 17919)

-----  
Point for the ¼ sec. cor. of sec. 27 only, is at midpoint in departure, on the S. bdy. of sec. 27.

From this point, the ¼ sec.cor. of sec. 27 only, erroneously established by Wofford, etal, 1973-79, bears S.70°18'W., 0.06 chs. dist., monumented with an iron post, 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. and witnessed as described in the official record.

Remove the iron post and at the true corner point, RESET the iron post 28" long, 2½" dia., 24" in the ground, with brass cap mkd: T 22 S R 9 W  
¼ S 27  
1984

from which bearing trees mkd. by Wofford, etal,  
A Fir 13" dia., bears N.70°E., 30 lks. dist. with healed blaze.  
A Fir 10" dia., bears N.52 ¾°W., 17 lks. dist., with healed blaze.