

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars under contract #202, dated March 11, 1875 - (DCSO records Vol. 4 Page(s) 1626)

-----  
Set Fir post, 3 ft. long, 18" in ground, 5" dia., from which  
A Fir, 50" dia., bears S.68°E., 22 lks.  
A Fir, 16" dia., bears N.80°W., 79 lks.

Cor. fd. & used March 29, 1895 in GLO survey by Elmer Worrick, under contract #632 - (DCSO records, Vol. 4 Pages 1703-4)

Dependent resurvey by Boyd W. Peterson & John A. Farmer, Cadastral Surveyors, under Group #1791, surveyed Oct. 1995/Feb. 1998. (DCSO records Vol. 52 Page(s) 19862)

-----  
Point for the ¼ sec. cor. of secs. 10 & 11 at proportionate distance using the irregular boundary method; there is no remaining evidence of the original corner.

Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.

T 22 S R 9 W  
                  ¼  
S 10 | S 11  
                  1996

from which

A fir, 12" diam., bears S.24°E., 20 lks., mkd. ¼ S11 BT.

A fir, 10" diam., bears S.43½°W., 55 lks., mkd. ¼ S10 BT.

Deposit a magnet in a white plastic case at the base of the stainless steel post.

Gary Smithers - For: Roseburg Resources Co. - Oct 2005 - M148-73

-----  
Found - 1996 BLM brass cap, DCSO recs Vol 52 Pg 19862  
13" D.Fir S.24°E., 3.2 ft. With healed face & tag  
11" D.Fir S.43°W., 36.3 ft. With healed face & tag  
New BTs- 15" D.Fir N.60°E., 16.6 ft., scribed T22 R9 ¼ S11 BT  
to spike set side center with bearing tree tag  
17" D.Fir N.70°W., 36.4 ft., scribed T22 R9 ¼ S10 BT  
to spike set side center with bearing tree tag