

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 4 Page(s) 1632-33)

-----  
Set an Alder post 40" long, 5" dia., for the ¼ sec. corner, from which

A Maple 5" dia., bears N.25°E., 24 lks. dist.

An Alder 8" dia., bears S.15°W., 21 lks. dist.

Douglas County Surveyors Office - James W. Byron, Surveyor - C.S. File 54/60 - Dec. 7, 1967-8

-----  
Corner searched for, not found. Find unrecorded 1¼" I.P. and steel cap. We find no BTs as called for or new BTs apparently set by International Paper Co.

BLM resurvey by Harvey Wofford; Wayne Rogers and Owen Chatters II, Cadastral Surveyors under Group #'s 811 and 1000 - surveyed Aug. 1973/Oct. 1979 - (DCSO records Vol. 40 Page(s) 16033)

-----  
The ¼ sec. cor., perpetuated by person(s) unknown, monumented with an iron pipe, 2" dia., firmly set, projecting 6" above ground, with top mkd. ¼. This position has been recognized as the corner since 1947, by Mr. Floyd V. Weatherly, a resident of the area for many years, and is accepted as the best available evidence of the original corner position.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, directly over iron pipe, with brass cap mkd:

T 22 S R 9 W  
                  ¼  
                  S 23 | S 24  
                          1973

from which new bearing trees:

An Alder 8" dia., bears N.74°E., 78 lks. dist. mkd. ¼ S24 BT.

A Maple 23" dia., bears S.75°W., 100 lks. dist. mkd. ¼ S23 BT.

Corner is located 20 lks. West of the center of Lutsinger Creek Road, gravelled, 30 lks. wide, bears N.5°E. and S.5°W.; also, 30 lks. East of Lutsinger Creek, 10 lks. wide, course N.40°W.

Found OK by R. Quimby, February 1997 - M124-42

continued next page

TOWNSHIP 22 RANGE 09 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Dependent resurvey by Edith M Forkner, Cadastral Surveyor, under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO records Vol. 55 Page(s) 21740)

-----  
The ¼ sec. cor. of secs. 23 & 24, monumented with an iron post, 2½" dia., firmly set, projecting 1" above ground, with brass cap (properly) mkd. from which the remains of the bearing trees mkd. by Wofford, Rogers, and Chatters in 1973-79

    An alder, 15" dia., bears N.74°E., 51.5 ft., with a healed blaze.

    A roothole bears S.75°W., 66.0 ft., with a down decayed maple, size indeterminate, alongside, no marks visible. and a new bearing tree

    An alder, 13" dia., bears S.43½°W., 18.3 ft., mkd. ¼ S23 BT on bark. Tree is on the E. bank of Lutsinger Creek, 25 ft. wide, course N.

An aluminum fence post is alongside the cor. Corner is located W., 25 ft. from Lutsinger Creek Road, graveled surface, 12 ft. wide, bears N.15°E. and S.15°W.

Brent Knapp - For: Roseburg Resources - 2/24/2025 - M184-62

-----  
Found - Brass cap marked "T22S R9W ¼ S23/S24 1973"  
    16" Maple N.08°E. 11.4' with healed blaze no record.  
    14" Alder S.43°W. 18.3' healed blaze.

New - Aluminum post N.62°E. 15.4'  
    Aluminum post S.48°E. 15.7'

OCRS COORDINATE SYSTEM  
COTTAGE GROVE-CANYONVILLE ZONE