

PRIMARY CORNER DESCRIPTION Center 1/4 Section 24

Alias	Description

Ronald Quimby, surveyed for Scott Timber Feb. 1997 - M 124-42

Set - A 5/8" aluminum rod with alum. cap marked "IP
TIMBERLANDS OPERATING CO." "UNLAWFUL TO DISTURB" RLS
1654 and stamped:

T 22 S R 9 W
C 1/4 + S 24

from which:

- 10" D.Fir S.60°W., 8.6 ft. scribed "C 1/4 S24 BT"
- 15" D.Fir N.20°E., 12.7 ft. scribed "C 1/4 S24 BT"
- 8" D.Fir N.45°W., 18.3 ft. scribed "C 1/4 S24 BT"
- 12" D.Fir S.77°E., 37.7 ft. scribed "C 1/4 S24 BT"

Dependent resurvey by Edith M Forkner, Cadastral Surveyor,
under Group #2149, surveyed Aug. 2006/Oct. 2006 - (DCSO
records Vol. 55 Page(s) 21738)

The center ¼ sec. cor. of sec. 24, established by Quimby, in
1997 and is accepted as the corner; monumented with an
aluminum rod, 5/8" dia., firmly set, with top flush with the
surface of the ground, with aluminum cap, loosely attached,
(properly) mkd.

from which the bearing trees mkd. by Quimby in 1997

- A fir, 16" dia., bears N.20½°E., 12.3 ft., with a healed
double blaze.
- A fir, 16" dia., bears S.76¾°E., 35.5 ft., with a healed
double blaze.
- A fir, 13" dia., bears S. 60° W., 8.5 ft., with a healed
double blaze.
- A fir, 9" dia., bears N.45°W., 18.3 ft., with a healed
double blaze.

An aluminum fence post is alongside the cor. and a steel
fence post with a 1979 BLM location tag bears N., 7½ ft
Corner is located near the NW. cor. of young timber, edge
bears S. and E.