

TOWNSHIP 22 RANGE 10 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 24 and 25

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by W.H. Byars, Deputy Surveyor under contract # 274 survey dated Sept. 10, 1877 (DCSO records Vol. 4 Page(s) 1738)

-----  
Set a Fir post, 5" dia., for ¼ sec. cor., from which  
A Fir 8" dia., bears North, 112 lks.  
A Fir 15" dia., bears S.15°W., 62 lks.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #718, surveyed June/Aug 1970 - (DCSO records Vol. 36 Page(s) 14848)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.  
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:  
1/4  $\frac{S\ 24}{S\ 25}$   
T 22 S R 10 W  
1970

from which  
A Hemlock 15" dia., bears N.25°E., 108 lks. dist. mkd. ¼ S24 BT.  
A Hemlock 26" dia., bears S.21¼°E., 27½ lks. dist. mkd. ¼ S25 BT.

Fd. OK, June 1983 by E. Wobbe - M 94-51

Brent Knapp - Crew: N. Fromdahl, J. Ogden, & W. Keady - 5/1/2023 - C.S. File 65/111-54

-----  
Found - 2½" Brass Cap (properly mkd).  
Rotten Hemlock Stump, N.25°E., 71.3', no marks remaining.  
34" Hemlock, healed blaze and tag. Record S.21¼°E., 18.2', actual location S.21°W., 18.2'  
New - 8" Hemlock, N.42°W., 14.0', scribed "¼ S24 BT"  
5' Aluminum Post, S.3°10'29"E., 46.8' (ON LINE)  
5' Aluminum Post, N.88°01'20"W 5.0' (ON LINE)  
Note - 15°E Compass Declination