

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 143700

PRIMARY CORNER DESCRIPTION M.C. on N. bdy. Sec. 6

Alias 833010 Description M.C. Right bank Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Harvey Gordon, Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 3 Page(s) 1262)

To right bank of Umpqua River at Indian Village.
Set post, from which
A Pine 6" dia., bears N.9°W., 53 lks. dist.
No tree near S. of line.

BLM resurvey by Glenn Goodson, Scott McIntyre and Scott McMullin, Cadastral Surveyors, under Group #1064 - Surveyed June/Sept. 1981 - (DCSO records Vol. 44 Page(s) 17186)

Point for the meander cor. of secs. 6 and 31, at record distance; there is no remaining evidence of the original corner.

Set an alum. post, 28" long, 2½" dia., 24" in the ground, in concrete, with alum. cap mkd: T 21 S R 12 W

S 31
S 6 MC
T 22 S
1981

No suitable trees available within limits.
Set a steel fence post alongside aluminum post.