

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 242200

PRIMARY CORNER DESCRIPTION M.C. So. bdy. Sec. 29

Alias <u>820820</u>	Description <u>M.C. West bank, East arm Eel Lake</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #534, dated Jan. 12, 1889 (DCSO records Vol. 5 Page(s) 2060)

-----  
A Fir 18" dia. on West bank of Eel Lake, which I mark as meander cor. to fractional secs. 29 and 32, MC T22S onE.; R12W S29 on N.; S32 on S. faces, from which

A Fir 36" dia., bears S.27½°(?)., 13 lks. dist. mkd. T22S R12W S32 MC BT.

A Fir 20" dia., bears N.40½°W., 11 lks. dist. mkd. T22S R12W S29 MC BT.

Survey by Ronald Stuntzner - Dec. 10, 1986 - M 103-31

-----  
Found - Orig. meander corner established by Thiel, 1889. Original cor. tree, 18" D.Fir now 29", uprooted into Lake. Cor. tree has healed faces on N. and S. sides and visible axed, opened face and found no marks.

Orig. BT, 36" D.Fir now 48" stump, S.27½°W., 8.6 ft. tagged, visible axed bark, no scribes found.

Orig. BT, 20" D.Fir now rotted remains, N.30°W., 7.3 ft. (Rec. N.40½°W., 11 lks.)

Set 3/4" Iron rod with 2" alum. cap in orig. position of uprooted corner tree, cap mkd: "T22S R12W MC S29 S32 1986 LS 2244".

New BT - 29" D.Fir N.39°W., 39.6 ft. scribed T22S R12W S29 MC BT.

Fd. OK, July 1990 - M 112-9