

PRIMARY CORNER DESCRIPTION So. 1/16 cor. betw. secs. 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Douglas County Surveyors Office - Janet Lundeen, Deputy - R. Smith and S. Flause, Crew - Sept/Dec. 1986 - C.S. 62/43-K and M 101-18

Set a 2 3/8" dia. brass cap marked:
Douglas County Surveyors Office
T 22 S
S 1/16
S17 | S16
R 12 W
1986

on a 1" dia. (1 1/4" O.D.) x 32" long galv. Iron pipe protruding 1 ft. above ground and surrounded by a 2 ft. dia. mound of stone.

New BTs -13" DBH Spruce scribed "S 1/16 S16 CS BT" on a double blaze bears N.0 1/4°E., 44.0 ft.
8" DBH Spruce scribed "S 1/16 S16 CS BT" on a double blaze bears S.08 1/4°E., 67.2 ft.
19" DBH Alder bark scribed "S 1/16 S16 CS BT" bears N.79°E., 24.3 ft.
22" DBH Alder scribed "S 1/16 S17 CS BT" on a double blaze bears S.12°W., 21.4 ft.

Monument is near bottom of very steep SE slope and approx. 15 ft. higher than a small creek running NE.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Jan. 30, 1992 - C.S. File 64/23-4

Found - 2 3/8" dia. 1986 DCSO brass cap on a 1 3/8" O.D. Iron pipe, protruding 6" above a 2 ft. dia. mound of sandstone.

Three BTs as recorded in 1986 found OK.

8" Spruce bearing S.8 1/4°E., 67.2 ft. is now down and out of position.

Position of S 1/16 cor. was in error because of a problem with tie made to SE cor. of Sec. 17 in 1986. Position of DCSO BC/IP is referenced, BC/IP is removed, I.P. measured 32" long.

Set a 5/8" x 30" long Iron rod with plastic DCSO cap at referenced BC/IP position. I.R. protrudes 4" above a 2 ft. dia. mound of sandstone.

The marks "RESET 1992" are added to DCSO brass cap. BC/IP is set at a newly determined position of the S 1/16 cor. BC/IP protrudes 5" above mound of sandstone.

Accessories:

(Cont. Next Page)

TOWNSHIP 22 RANGE 12 POINT IDENTIFIER # 300420

PRIMARY CORNER DESCRIPTION So. 1/16 cor. betw. secs. 16 & 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

13" now 14" dia. Spruce with a partially healed double blaze, scribing visible "S 1/16 S17 CS BT" (S16 changed to S17) bears N.4½°W., 52.2 ft.
19" now 20" dia. Alder with a partially healed double blaze, scribing visible "S 1/16 S16 CS BT" bears N.58°E., 24.5 ft.
22" now 23" dia. Alder with a partially healed double blaze scribing visible "S 1/16 S17 CS BT" bears S.33½°W., 14.9 ft.
5/8" Iron rod with plastic DCSO cap bears N.23 3/4°W., 8.9 ft.
Corner lies near the bottom of a steep slope approx. 20 ft. NE running creek. Bearings taken with staff compass.