

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Harvey Gordon Deputy Surveyor, under Contract #69 dated Feb. 2, 1857 (DCSO records Vol. 5 Page(s) 2122)

-----  
Set qr. sec. post, drove charred stake.

Survey by John E. Hollingsworth, Oregon State parks Survey for Umpqua Lighthouse State Park - Wit: R. Mills; L. Goge; T. DeSouza; E. Woods - 8/26/1977 - C.S. File 58/152 & M 66-64

-----  
Set 3/4" x 5 ft. Iron pipe, from which  
Steel post with white paddle marked "OREGON STATE PARK BOUNDARY DO NOT DISTURB", 2 ft. East of iron pipe.  
A nail with rounded head and a 2" dia. shinner in pavement of road, N.71°30'E., 178.17 ft.  
A Coast Guard telegraph pole, S.3°30'E., 189.57 ft. to a PK nail on West side of pole, 4 ft. above ground.

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1122 - surveyed Oct. 1982 - (DCSO records Vol. 44 Page(s) 17068)

-----  
The ¼ sec. cor., monumented with an iron pipe, 1" dia., firmly set, flush w/ the surface of the ground, reestablished & recorded by Hollingsworth, in 1977, & is accepted as the best available evidence of the original corner.  
Set an iron post, 28" long, 2½" dia., 24" in the ground, directly over the iron pipe, in concrete, with brass cap mkd:  
T 22 S R 13 W  
1/4  
S 14 | S 13  
1982

No suitable trees available within limits.  
Set a steel fence post alongside the iron post.  
From this same point, Oregon State Highway Dept. triangulation station "GUARD", 1968, bears N.57°51'E., 23.73 chs. dist., monumented with a standard brass tablet, 3¾" dia., set in a concrete post, 9" dia., firmly set, projecting 9" above the ground, mkd. GUARD 1968.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Jan. 5, 1988 - C.S. File 62/49-1 (M101-35)

-----  
Found - 1983 BLM 3¾" brass cap on a 2¼" I.P. protruding 7" above ground.  
1" I.P. from 1977 was not looked for. It lies under BC/IP according to 1982 BLM line notes.  
No other monuments previous to 1977 were found.  
(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Nail with round head and a 2" shiner in AC now covered by an AC overlay, nail located with metal detector (not uncovered), bears N.71½°E., 178.17 ft., agrees with record.  
Coast Guard telephone pole with PK nail on West side 4 ft. above ground now pole cut down and remainder protrudes 5 ft. above ground, bears S.3½°E., 189.57 ft. agrees with record.  
Steel post with white paddle bears S.49°E., 1.7 ft. (Rec. East, 2 ft.) (1977)  
OSHD station "Guard 1968" has a record bearing and distance of N.57°51'E., 23.73 chains. Station Guard is OK, bearing and distances not checked.  
New BTs - 5" Spruce double blazed and scribed "¼ S14 CS BT" bears N.55½°W., 32.6 ft.  
6" Spruce double blazed and scribed "¼ S13 CS BT" bears S.10°E., 12.0 ft.  
Perpetuated as point. Projected by Hollingsworth and accepted by BLM for corner location.

FD ok by Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 3/31/2004 - C.S. File 67/6-12B

Douglas Co. Surveyors Office - Stephen J. Flause - John Pike - 2/19/2007 - C.S. File 67/21-20

-----  
Found - 1983 BLM 3¼" dia., brass cap (properly mkd) on 2¼" IP projecting 6" above ground.  
5" now 9" spruce, fully healed double blaze, bears N.55½°W., 32.6 ft. (agrees w/rec) 1988 BT  
6" now 9" spruce, fully healed double blaze, bears S.10°E., 12.0 ft. (agrees w/rec) 1988 BT  
Steel post w/white paddle sign bears S.49°E., 1.7 ft. agrees w/rec.  
No other accessories looked for.  
New - 5/8" dia., x60" long iron rod, no cap, bears S.12°15'W., 141.61 ft.  
Boat spike in edge of rd, driven flush, bears S.28°54'33"E., 169.44 ft.  
Basis of bearing back sight staff compass. See sketch of referenced corner in file.  
Note - Located Northwesterly of intersection of Salmon Harbor Dr. & Beach Access Rd.  
Additional accessories were added because corner was in danger of being destroyed due to construction of new campground to the North

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 600440

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 13 and 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Fd. BC by M Heimburger, 4/2014 - M168-25

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 9/5/2025 - C.S. File 67/61-22

-----

Found - 3/4" BLM brass cap flush with ground.  
11" spruce N.55 1/2°W. 32.6 ft fully healed double blaze. Add 3 1/2" mag nail right side center.  
10" spruce S.10°E. 12.0 ft. Fully healed double blaze. Add 3 1/2" mag nail right side center.  
Steel post with white paddle sign S.49°E. 1.7 ft  
5/8" Iron rod S.12°15'W. 141.6ft. No cap, flush with ground.  
Boat spike in edge of road S.28°54'33"E. 169.44 ft  
Top 2" bend north.

Compass decl. 14 1/2°E.  
O CRS COORDINATE SYSTEM  
COTTAGE GROVE-CANYONVILLE ZONE  
43°39'40.92219" N.  
124.12'13.34246" W.