

TOWNSHIP 22 RANGE 13 POINT IDENTIFIER # 640140

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 36

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM resurvey by Glenn F. Goodson, Rick E. Tawney, Elma Jean Acuna, Cadastral Surveyors, under Group #1122 - surveyed Oct. 1982 - (DCSO records Vol. 44 Page(s) 17070)

Point for the center ¼ sec. cor. of sec. 36, at the intersection with the E. and W. center line.
Set an alum. rod, 19 ft. long, 5/8" dia., 18½ ft. in the ground, in concrete, with alum. cap mkd: T 22 S R 13 W
C 1/4 S 36
1982

from which
A Fir 15" dia., bears N.28°E., 659½ lks. dist. mkd. C ¼ S36 BT.
No suitable tree available to the E. within limits.
Set a steel fence post alongside the aluminum rod.

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - July 28, 1993 - C.S. File 64/46-8

Found - 5/8" dia. alum. rod and metal fence post, both in an 18" dia. x 6" deep concrete base. Alum. rod and fence post are bent over westerly, alum. rod protrudes 5 ft. out of sand. (1982 BLM). Alum. rod is plumb, going into sand. Area is subject to heavy ATV use, monument appears to have been bent over to protect ATV users.
15" now 14" dia. dead D.Fir with a small diamond shaped axe blaze and nail in bark. Dug in sand along base approx. 2½ ft., no blazes found, bears N.28°E., 431.7 ft. (Rec. N.28°E., 435.3 ft.)

New Accessories:
20" DBH D.Fir, bark scribed "C ¼ S36 CS BT" bears N.21¼°E., 466.0 ft.
Center of tall, narrow house (only structure in sight) bears S.80½°E.
Corner lies in sand dunes. No other trees within reasonable distance.