

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by James P. Currin, Deputy Surveyor, under contract #438, dated May 3, 1882 - (DCSO records Vol. 6 Page(s) 2245)

Set a post 4 ft. long 4" sq. 24" in the ground for cor. to secs. 28, 29, 32 & 33 mkd. T23S S28 on NE, R3W S33 on SE, S32 on SW, and S29 on NW, faces with 1 notch on S and 4 notches on E edges from which

- A Fir, 30" dia. bears N.30°E. 25 lks. mkd: T23S R3W S28 BT
- A Fir, 60" dia. bears S.80°E. 50 lks. mkd: T23S R3W S33 BT
- A Hemlock, 15" dia., bears S.10°W., 60 lks., mkd: T23S R3W S32 BT.
- A Fir, 36" dia. bears N.40°W., 5 lks. mkd: T23S R3W S29 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy -Oct. 26, 1967 - C.S. File 54/16-25

Found unrecorded ren. of corner.
Found ½" I.P. called for in Forrest appraisal notes - & Weyerhaeuser method BTs as follows -
30" Fir stump N.37°E, 15.6 ft. "W" nail & tag - pocket knife scribe "BT S28" Not orig. scribe.
48" Fir stump S.60°E., 31.0 ft. "W" nail & tag - no scribe
48" Fir stump N.48°W., 3.2 ft. "W" nail & tag - no scribe.
24" Hemlock S.69°W., 29.8 ft. live tree - "W" nail & tag - no scribe. We find no orig. scribe mks.

Dave Wellman, LS 2163 - For: Weyerhaeuser Co. - Erin Heatherstone & Micah Johnstone - June 2003 - C.S. File 65/45-

Found - ½" iron pipe lying on ground.
Decayed 30" Fir stump, WEYCO tag reads S.37°W., 15.6 ft. - Tag & "W" nail
Decayed 48" Fir stump, WEYCO tag reads N.60°W., 31.0 ft. Tag, no "W" nail fd.
Decaying 48" Fir stump, WEYCO tag reads S.48°E., 3.2 ft. Tag & "W" nail
31" Hemlock WEYCO tag reads N.69°E., 29.8 ft. Tag & "W" nail.
Set - 1¾"x36" iron pipe with 2½" brass cap dated 2003
11" Fir N.46½°E., 16.7 ft. to spike set side center, scribed "T23S R3W S28 BT"
13" Fir N.48°W., 9.5 ft. to spike set side center, scribed "T23S R3W S29 BT"
15" Fir S.27½°E., 22.9 ft. to spike set side center, scribed "T23S R3W S33 BT"
Corner is 50 ft. West of 2002 clear cut.