

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 140200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 30 & 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855  
(DCSO records Vol. 6 Page(s) 2286)

-----  
Set ¼ Sec. post from which  
A Fir, 4" dia., bears S.37°E., 19 lks.  
A L.Oak, 18" dia., bears N.55°W., 27 lks.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under  
Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41  
Page(s) 16159)

-----  
Search was made for the ¼ sec. cor. of secs. 30 & 31, no  
evidence of which was found.

Ron Quimby - For: O.E. Kingzette - May 1981 - M 79-77

-----  
Set - 5/8" iron rod at proportionate distance.  
8" Madrona bears S.55°E., 4.2 ft., scribed ¼ S31 BT.  
12" Madrona bears N.38°E., 45.8 ft., scribed ¼ S30 BT.  
Note- No orig. evidence of corner found.  
¼ cor. bears 13 ft. East of creek & 15 ft. North of  
fence.

David Edwards - For: Oxbow Timber 1 LLC - June 2018 - M174-43

-----  
Found - 5/8" IR  
A 14" dia. Madrone bears N.38°E., 45.8 ft.  
The madrone S.55°E., 4.2 ft per M 79-77 is gone.  
New BT - A 10" dia. Fir scribed "¼ S30 BT" bears N.88°E.,  
10.0 ft.  
No BT available in section 31.