

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 30

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855 (DCSO records Vol. 6 Page(s) 2287)

Set ¼ Sec. post from which
 A Cedar, 4" dia., bears S.85°W., 50 lks.
 A Yew, 12" dia., bears N.56°W., 60 lks.

O.F. Thiel - For: Pringle Bros. - 11/1926 (recorded 9/1/1998) - F.B. 116 Pg. 11

SW tree cut down. Found old marks on N.W. (Yew) tree. Remarkd same. Set a cedar post and marked:
 A Fir 20" S.84°W., 28

Oscar Thiel - Marion Bigalow & Donald Bigalow witnesses - 1942 (Added to records 3/21/1984) - C.S. 61/5-1 & FB 117 pg 21

Set a Cedar post from NE BT, the other BT cut down. The marks on NE BT were yet visible but badly decayed, obliterated, so I remark the old tree:
 A yew 16" dia., bears N.56°W., 60 lks.
 A Fir 20" dia., bears S.84°W., 42 lks.

Milo E. Godfrey, Deputy Co. Surveyor - Vernon Tracy - Mike Stone - May 17, 1963 - C.S. File 53/9-6

Found - 1½" steel shaft, 9" above ground mkd: **4**
 on top. No record.
 A 28" D.Fir, bears S.88°W., 16.4 ft., scribing "¼" visible on badly face. Not orig. tree.
 A badly burned & hollow Yew stump, no markings, bears approx. bearing & dist. for orig. NW BT.
We have no record of any renewal for this corner. A yellow tag on the Fir has the name "L.J. Martin" dated "10-22-54".
DID NOT RENEW CORNER

BLM resurvey by James E. Jelley, Cadastral Surveyor, under Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41 Page(s) 16162-63)

From the ¼ sec. cor. of secs. 19 & 30, perpetuated by person(s) unknown, monumented with an iron rod, 1" dia., firmly set, projecting 8" above ground, from which the remains of the orig. BTs:
(Cont. next page)

