

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
 (DCSO records Vol. 6 Page(s) 2281)

 Set 1/4 Sec. post from which
 A Fir, 12" dia., bears N.81°E., 50 lks.
 A Cedar, 40" dia., bears N.17°W., 24 lks.

BLM resurvey by James E. Jelley, Cadastral Surveyor, under
 Group #895 - Surveyed June/Sept. 1976 (DCSO records Vol. 41
 Page(s) 16156)

 Point for 1/4 sec. cor. at proportionate distance; there is no
 remaining evidence of the orig. corner.
 Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with
 brass cap mkd:
 1/4
 S 17 | S 16
 T 23 S R 4 W
 1976

from which
 A Fir, 14" dia., bears S.14 3/4°E., 25 lks., mkd: 1/4 S16 BT
 A Fir, 13" dia., bears N.40 1/2°W., 20 1/2 lks., mkd: 1/4 S17 BT

Found OK by C. Sweeden, May 2001 - LP 2001-0041

BLM Dependent resurvey by A. Bert Skeesick, Cadastral
 Surveyor and Robert H. Browning, Surveying Technician under
 Group No. 2172 - Surveyed July/Nov. 2007 - (DCSO records Vol.
 55 Page(s) 21542-3)

 The 1/4 sec. cor. of secs. 16 and 17, monumented with an iron
 post, 2 1/2 ins. diam., firmly set, projecting 3 ins. above
 the ground, with brass cap (properly) mkd.
 from which the remains of bearing trees mkd. by Jelley
 A decayed fir stump, size indeterminate, bears S.14 3/4°E.,
 16.5 ft., with no marks visible.
 A fir, 21" dia., bears N.40 1/2°W., 13.5 ft., with a healed
 double blaze.
 and a new bearing tree
 A fir, 10" dia., bears N.54 1/4°E., 41.2 ft., mkd. 1/4 S16 BT

Fd. BC & 2 BTs by Ken Hoffine, Nov. 2016 - M172-80