

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 400440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Gordon & Gardner, Contract #52 dated Feb. 1855
(DCSO records Vol. 6 Page(s) 2275)

Set ¼ sec. post, from which
A fir, 15" dia., bears N.84°W., 6 lks.
A fir, 30" dia., bears N.76°E., 22 lks.

Symbol on corner renewal visual pg is "Looked for not FD"
No written report fd.

BLM Dependent resurvey by Timothy J. Moore, Cadastral
Surveyor & Robert Browning, Surveying Technician under Group
#1955, surveyed 2000/2001 (DCSO rec. Vol. 54 pg(s) 20851)

Point for the ¼ sec. cor. of secs. 15 & 16, at proportionate
distance, there is no remaining evidence of the original cor.
Set a stainless steel post, 28" long, 2½" diam., 23" in the
ground, with brass cap mkd.

T23S R4W
¼
S 16|S 15
2000

from which
A cedar, 7" dia., bears N.53¾°E., 24.2 ft., mkd. ¼ S15 BT.
A fir, 12" dia., bears N.80¾°W., 17.6 ft., mkd. ¼ S16 BT.
Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail)
driven at the base right side-center.

Deposit a magnet in a white plastic case at the base of the
stainless steel post.
Corner is located S. 85¼° E., 31.3 ft., from the corner of
woven wire fences, fences extending north and east.