

TOWNSHIP 23 RANGE 04 POINT IDENTIFIER # 640300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 24 & 25

Alias	Description
Alias	Description
Alias	Description
Alias	Description

<p>Original - William P. Wright, Deputy Surveyor, under Contract No. 514, dated Aug. 27, 1884 (DCSO records Vol. 6 Page(s) 2304)</p> <p>-----</p> <p>Set post 4" dia., 4 ft. long, with marked stone 12" in ground for ¼ sec. cor. mkd: ¼ S on N face, from which</p> <p> A Fir, 36" dia., bears N.28°E., 33 lks., mkd: ¼ S BT.</p> <p> A Fir, 40" dia., bears S.12°E., 18 lks., mkd: ¼ S BT.</p>
<p>Weyerhaeuser Co. - 1944 (added 11/10/2020) - C.S. File 53/108-7 for 1944</p> <p>-----</p> <p>Found - 40" Fir, N.28°E., 21.8 ft. (Orig. BT)</p> <p>New - 70" Fir N.53°W., 23.8 ft</p>
<p>Wilford Haines - Survey date unknown, filed Dec. 1965 - C.S. File 54/16-23K</p> <p>-----</p> <p>Found - 36" Fir, N.28°E., 33 lks., no visible scribe.</p> <p> 40" Fir, S.12°E., 18 lks., down.</p> <p>Scribed- 16" Hemlock, S.64°E., 25.0 ft.</p> <p> Re-barked scribed Fir, N.28°E., 33 lks.</p>
<p>Weyerhaeuser Co. - 1959 thru 1962 - C.S. File 53/108-8</p> <p>-----</p> <p>Found - 36" Fir, N.28°E., 21.8 ft., down, badly splintered</p> <p> 40" Fir. (Orig. BT)</p> <p> 40" Fir, S.12°E., 12.9 ft., down, long butt moved by logging.</p> <p> Haines "T" iron in proper corner position.</p> <p>BTs - 70" Fir, N.54°W., 23.0 ft., "W" plate & nail.</p> <p> 8" Hemlock, S.7°W., 24.9 ft. "W" plate & nail.</p>
<p> </p>