

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by Gordon and Gardner, under Contract #52 dated Feb. 17, 1855 (DCSO records Vol. 4 Page(s) 1388)

-----  
Set ¼ sec. post, from which  
A Fir 18" dia., bears N.15°E., 21 lks. dist.  
A Fir 12" dia., bears N.30°W., 20 lks. dist.

Survey by Wilford N. Haines - June 1960 - M 19-6

-----  
Found - 2 stumps that fit for bearing and distance of orig. BTs.  
20" Fir snag, scribed ¼ S BT, S.86°W., 13.2 ft.  
Set 1" x 1" x 36" T-Iron, ¼ S32, not on line.

Fd. OK, Eugene Bloom, June 1981, M 79-79

BLM resurvey by James E. Jelley and Wayne L. Rogers, under Group #1119, surveyed Oct. 1982/Feb. 1984 (DCSO records Vol. 46 Page(s) 17669)

-----  
The ¼ sec. cor. of sec. 32 only, perpetuated and recorded by Haines in 1960, monumented with a "T" shaped iron rod, 1" dia., firmly set, projecting 8" above ground, from which the remains of an original bearing tree:

A decayed Fir stump, size indeterminate, bears N.15°E., 21 lks. dist., no marks visible.  
and the remains of a bearing tree mkd. by Haines:  
A Fir snag 13" dia., bears S.85°W., 20 lks. dist., with scribe marks ¼ S BT visible on open blaze.  
and a bearing tree mkd. by person(s) unknown:  
A Fir 37" dia., bears N.21°E., 40 lks. dist., with healed double blaze.  
No new monument established.

DCSO-GIS Corner visitation - 11/30/2005 - Typed: 1/13/2011 - C.S. File 67/33-1

-----  
Monument - "T"-iron                      Comment - in new clearcut; 2 capped stumps.

Douglas Co. Surveyors Office - Stephen J. Flause - Mike Koch - Sept. 30, 2013 - C.S. File 67/40-12

-----  
Found - A 1"x1"x36" T-Iron now a 1x1" Haines "T" iron (missing brass ID washer) is firmly protruding 4" above ground. 1960  
No clear evidence remains of OBTs or their stumps; area was logged and burned.                      cont. next page

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

No clear evidence remains of 1982-84 BLM BTs  
Two stumps with apparent healed double blazes facing the corner monument. Blazes are opened but no scribing is fd. Faces appear to have never been marked. No rec. is fd. for origin. (These 2 stumps will become new accessories)

New - The two previously noted, fd. blazed stumps of unknown origin:\*

- \*A 13" dia., 3 ft. tall D.Fir stump with a partially opened double blaze; bears N.37½°E., 13.4 ft.
- \*An 11" dia. 3 ft. tall D.Fir stump with a partially opened double blaze; bears N.27¾°W., 15.3 ft.

An 8" long galvanized iron spike ¾" in dia., at its top is driven into the top of and plumb over the C.R. C. of, a 36" dia., 2½ ft. tall D.Fir stump which bears S.43½°W., 10.0 ft.

A green and white metal fence post protruding 3 ft. above ground; bears N.15°E., 1 ft. dist.

All live trees in area are too small to mark.  
(Sketch shows that a forest access road center line is "EAST 40' " from the corner.)

Note - Monument is on steep NW slope just off the top of a high NE running ridge in young fir reprod with old fir forest on SE side of ridge.  
Compass decl. 15½°E.