

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 33 & 4 T24-5

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Robert Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records Vol. 6 Page(s) 2345)

-----  
Set ¼ sec post, from which  
A Y.Oak, 18" dia., bears N.23°E., 32 lks.  
A Y.Oak, 28" dia., bears S.39°E., 33 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Deputy & crew - C.S. File 54/16-67 - 1969

-----  
Corner not found.  
Approx. location from creek call to east falls in old cat log trails - No OBTs found.

David Edwards - For: Roseburg Resources - 3/2020 - M176-69

-----  
At mid-point  
Set - 5/8"x30" steel rebar with 2½" dia., alum. cap mkd as per the 2009 BLM Manual and also mkd: "ROSEBURG RESOURCES CO." and "LS 2339" AND "2020"  
A 15" dia., Fir scribed "T23S R5W ¼ S33 BT" bears N.48°E., 15.4'  
A 10" dia., Oak scribed "T24S R5W ¼ S4 BT" bears S.1°E., 22.5'  
6 ft steel posts are set 2 ft east and south.