

TOWNSHIP 23 RANGE 05 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Robert Elder and Henry Gile, Deputy Surveyors,
under Contract #31 dated April 7, 1853 (DCSO records Vol. 6
Page(s) 2349)

Set $\frac{1}{4}$ post, from which
A W.Oak, 16" dia., bears S.25°W., 111 lks.
A Y.Oak, 18" dia., bears N.41°E., 177 lks.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy, Deputy &
crew - C.S. File 54/16-67A - 1969

Corner not found.
No OBTs found, now 2nd growth fir.

Mark Smalley - For: Roseburg Resources - Oct./Nov. 2002 -
M137-55

Set - 5/8"x 48" iron rod and aluminum cap marked "LS 2354
2002" 17" above ground.
BTs - 14" Oak S.77°W., 59.6' scribed "1/4 BT"
9" Fir S.2°E., 56.5' scribed "1/4 BT"
8" Fir S.37°W., 85.8' scribed "1/4 BT"
17" Fir S.24°E., 36.5' scribed "1/4 BT"
Corner lies 15' North of E-W fence by natural gas line.

FD. ok by D. Edwards 9/2005 - M148-40

Fd. Ok by Douglas Co. Surveyors Office - Stephen J. Flause -
John Pike - 5/15/2007 - C.S. File 67/21-38