

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25 of T23-7

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by W.H. Byars, Deputy Surveyor under contract # 376 survey dated Jan. 22, 1881 (DCSO records Vol. 6 Page(s) 2391)

-----  
Set ¼ sec. post, from which  
A Fir 16" dia., bears N.10°E., 33 lks.  
A Fir 36" dia., bears S.55°W., 85 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12651)

-----  
Point for the ¼ sec. cor. of secs. 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 30" long, 2" dia., 12" in the ground, to solid rock, and in a mound of stone, 4 ft. base, to top, with brass cap mkd:

T23S  
¼  
R7W|R6W  
S25|S30  
1957

from which  
A Fir 10" dia., bears S.7°E., 136 lks. dist., mkd. ¼ S30 BT.  
A Fir 13" dia., bears N.25°W., 92 lks. dist., mkd. ¼ S25 BT.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #244, Surveyed April/May 1964 (DCSO records Vol. 32 Page(s) 13500)

-----  
The ¼ sec. cor., determined at record bearing and distance from the remaining original bearing tree:

A Fir 62" dia., bears S.55°W., 85 lks. dist., with fragmentary scribe marks visible on double bark blaze. From this point, the ¼ sec. cor, erroneously reestablished by Eggen, in 1957, bears S.42°42'E., 0.916 chs. dist., set, marked and witnessed as described in the official record. I remove the iron post, destroy the marks on the bearing trees, and at the original corner point Rest the iron post, 28" long, 2½" dia., 20" in the ground, to bedrock, and in a mound of stone, 2½ ft. base, to top, with brass cap mkd:

T 23 S  
¼  
R 7 W|R 6 W  
S 25|S 30  
1957

(Cont. Next Page)

TOWNSHIP 23 RANGE 06 POINT IDENTIFIER # 100240

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 30; & 25 of T23-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which new bearing trees A Fir 10" dia., bears N.47°E., 12½ lks., mkd. ¼ S30 BT. A Fir 25" dia., bears S.82°W., 43 lks., mkd. ¼ S25 BT.
David Edwards - For: Roseburg Resources - May 2005 - M147-56 ----- Found - BLM brass cap 18" Fir N.47°E., 8.3', healed blaze. 30" Fir stump S.82°W., 28.4', healed blaze. Set - 6' steel post 2' steel.