

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by John A. McQuinn, Deputy Surveyor, under Contract #466, dated April 5, 1883 (DCSO records Vol. 6 Page(s) 2432)

Set a Yew post 3 ft. long, 3" sq., 24" in the ground for ¼ sec. cor., mkd. ¼ S on N. face, from which
A Fir 30" dia., bears S.70°E., 40 lks. dist. mkd. ¼ S BT.
A Fir 40" dia., bears N.41°E., 34 lks. dist. mkd. ¼ S BT.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12693-94)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 30" long, 2" dia., 18" in the ground to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:
T23SR6W
¼ $\frac{S\ 21}{S\ 28}$
1957

from which
A Fir 34" dia., bears N.20°E., 5 lks. dist. mkd. ¼ S21 BT
A Fir 10" dia., bears S.43°30'E., 144 lks. dist. mkd. ¼ S28 BT.

BLM Corrective Dependent Resurvey by Wayne L. Rogers; Boyd W. Peterson; Philip G. Griffin; Dale T. Bedell; Cadastral Surveyors; and Robert H. Browning, Surveying Technician - under Group #'s 1266, 1637 and 1688, - surveyed June 9, 1986/Aug. 22, 1995 - (DCSO records Vol. 51 Page(s) 19496-97)

Point for the ¼ sec. cor. at proportionate distance. There is no remaining evidence of the original corner.
Set a stainless steel post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd.
T23S R6W
S21
¼ -----
S28
1994

from which bearing trees mkd. by Gould, Gawron, and Eggen
A fir, 36 ins. diam., bears S. 20½° E., 118 lks. dist., with healed blaze.
A fir, 54 ins. diam., bears S. 88¼° W., 56 lks. dist., with healed blazes on S. and W. sides.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 21 and 28

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

and a new bearing tree

A chinquapin, 6 ins. diam., bears N. 5½° W., 43 lks. dist., mkd. ¼ S21 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

From this point, the ¼ sec. cor. of secs. 21 and 28, erroneously reestablished by Gould, Gawron, and Eggen in 1943-57, bears S. 83° 19' 00" W., 0.593 chs. dist.; monumented with an iron post, 2½ ins. diam., firmly set, projecting 15 ins. above the ground, with brass cap marked and witnessed as described in the official record. Amended the marks on the brass cap to read AM 1994 1957 and reset the monument inverted.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22853)

The ¼ sec cor. of secs. 21 & 28, monumented with an iron post, 2½" dia., firmly set, projecting 2" above ground, with a brass cap (properly) mkd.

from which bearing trees mkd. by Gould, Gawron, and Eggen

A fir, 42" dia., bears S.20½°E., 77.9 ft., with a healed blaze.

A fir, 56" dia., bears S.88¼°W., 37.0 ft., with a healed blaze.

and a bearing tree mkd. by Rogers, et al, in 1986-95

A chinquapin, 9" dia., bears N.5½°W., 28.4 ft., with a healed blaze.

From this cor., a point erroneously reestablished by Gould, Gawron, and Eggen, bears S.83°17'41"W., 38.47 ft., monumented with an iron pipe, 2½" dia., firmly set, top 4" below ground surface.

Corner is located 35 ft. E. of a ridge, bears N.30°W. and S.30°E., and 85 ft. E. of a gravel road, 14 ft. wide, bears N.40°W. and S.40°E.

NAD 1983 (CORS 96)

Latitude: 43°32'52.51"N. Longitude: 123°24'57.21"W.