

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 35; and 2, T24-6

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Robert Elder & Henry Gile, Deputy Surveyors, under Contract #31 dated April 7, 1853 (DCSO rec Vol 6 Pg 2387)

Set 1/4 sec. post, from which
A Fir 14" dia., bears N.37°W., 33 lks.
A Fir 15" dia., bears S.23°E., 18 lks.

BLM resurvey by Otis Gould, Joseph Gawron, and Orville Eggen, Cadastral Surveyors, under Group #244, surveyed June 1943/October 1957 (DCSO records Vol. 30 Page(s) 12643)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, with brass cap mkd:
1/4 S 35
S 2
1943

from which
A Fir 40" dia., bears N.19°E., 58 lks., mkd. 1/4 S35 BT.
A Fir 20" dia., bears S.24°W., 48 lks., mkd. 1/4 S2 BT

Found OK by D. Edwards, May 2002 - M140-13

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2308, Surveyed April/July 2010 - (DCSO records Vol. 57 Page(s) 22830)

The 1/4 sec. cor. of secs. 2 and 35, on the S. bdy of the Tp., perpetuated by Edwards, in 2002, monumented with an iron post, 1" dia., firmly set, projecting 11" above ground, with a brass cap (properly) mkd.
from which the remains of BTs mkd. by Gould, Gawron, & Eggen
A decayed fir stump, size indeterminate, bears N.23 1/2°E., 38.3 ft., with no marks visible. (Record, N.19°E.)
A roothole bears S.24°W., 31.7 ft., alongside of which is an uprooted, sawed, decayed fir stump, size indeterminate, with no marks visible.
and bearing trees mkd. by Edwards
A fir, 28" dia., bears N.50 3/4°E., 15.9 ft., with a healed blaze.
A fir, 6" dia., bears S.54 3/4°W., 28.5 ft., with fragmentary scribe marks visible on a partially healed blaze.
A fir, 15" dia., bears N.8°W., 20.8 ft., with a healed blaze.

NAD 1983 (CORS 96)
Latitude: 43°31'09.87"N. Longitude: 123°22'33.97"W.