

PRIMARY CORNER DESCRIPTION So. 1/4 Cor. for Sec. 31 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2461)

Marked a Yellow Fir 3" dia., for ¼ sec. post, from which
A Fir 6" dia., bears N.20°E., 7 lks. dist.
A Fir 20" dia., bears S.46°E., 45 lks. dist.

BLM resurvey by G. Albert White and Donald R. Beck, Cadastral Surveyors under Group #515, Surveyed Jun/Oct. 1963 - (DCSO records Vol. 32 Page(s) 13479)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd:
T 23 S R 7 W
¼ S 31
1963

from which
A Fir 16" dia., bears N.43°E., 60½ lks., mkd. X at breast height and BT at base of tree.
A Fir 10" dia., bears N.53°W., 95 lks. mkd. ¼ S31 BT.

Fd. OK, March 1983 by D. Bentz - M 90-38 A&B

Douglas Co. Surveyors Office - Stephen J Flause - Mike Koch - Aug. 26, 2014 - C.S. File 67/41-56

Found - 1963 3¼" dia., brass cap (properly mkd) on a 2" I.D. iron pipe set plumb protruding 3" above ground. No OBT evidence remains.
A fir 16" dia., now a 24" dia., 2 ft. tall sawed and rotted fir stump with clear blaze evidence at 16" dia., but with no scribing remaining; bears N.41°E., 39.9 ft. (rec. N.43°E., 39.9 ft.) 1963 NW BT falls in skid road, no evidence found.
New - 25" dia., G.Fir scribed "¼ S31 CS" "BT" on a double blaze; bears N.69°E., 8.2 ft.
9" dia., G.Fir scribed "¼ S31 CS" "BT" on a double blaze; bears N.45°W., 19.1 ft.
6" dia., D.Fir scribed "X" "CSBT" on a high-low blaze; bears N.7½°W., 10.2 ft.
Note - Monument is on very gentle south slope, in old reprod of mixed fir and some cedar. An older clear-cut is in NE quadrant.
Compass decl. 15½°E.