

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 169200

PRIMARY CORNER DESCRIPTION M.C. on South bdy. Sec. 30

Alias 870120 Description M.C. on left bank Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2490)

Left bank of Umpqua River where marked a crooked Maple 14" dia. for cor. to fractional secs. 30 and 31, from which
A Fir 24" dia., bears N.44°W., 27 lks. dist.
A W.Fir 26" dia., bears S.50°E., 10 lks. dist.

BLM resurvey by Floyd A. Brooks, Cadastral Surveyor, under Group #456, Surveyed Aug 1961/Jan. 1962 (DCSO records Vol. 31 Page(s) 13081)

The meander corner is determined at record bearing and distance from the only remaining original bearing tree:
A Fir 50" dia., bears N.44°W., 27 lks. dist. with a healed blaze.

At the corner point
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, and in a mound of stone, 2 1/2 ft. base, to top, with brass cap mkd. with brass cap mkd:
T 23 S R 7 W
S 30 \ MC
S 31 \
1961

from which
A Fir 15" dia., bears S.58 1/2°W., 30 1/2 lks. dist. mkd. T23S R7W S31 MC BT.

Fd. and used in BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1102, surveyed July/Aug. 1982 - (DCSO records Vol. 46 Page(s) 17601)

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 4/17/2003 - C.S. File 66/58-6

Found - 1961 BLM brass cap/iron pipe protrudes 4" out of ground on small shelf of river bank approx. 1/3 way between water & high bank.
24" now 50" dia. D.Fir with a healed blaze bears N.44°W., 17.8 ft. (OBT)
15" now 20" dia., D.Fir with a fully healed single blaze bears S.58 1/2°W., 19.8 ft. (1961)
New - 25" dia., D.Fir double blazed & scribed "T23S R7W S31 MC BT" bears S.77 1/2°W., 32.0 ft.
44" dia. triple trunked D.Fir double blazed & scribed "T23S R7W S31 MC BT" bears S.29°W. 24.6 ft

continued next page

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 169200

PRIMARY CORNER DESCRIPTION M.C. on South bdy. Sec. 30

Alias 870120 Description M.C. on left bank Umpqua River
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Following positions are for location purposes only

NOT SURVEY GRADE

Equipment: Trimble GEOEXPLORER 3 System

File: R041720A

Point Name: T23SR7W S31WMC

<u>1927</u>		<u>1983</u>	
OCS	N 695377	E 1187179	N E
Latitude:	43°32'02.0"		Latitude:
Longitude:	123°33'57.1"		Longitude:
Offset to corner?	Yes		
Corrected for?	Yes		

