

PRIMARY CORNER DESCRIPTION Sec Cor for 3 and 10 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

<p>GLO survey by Thomas H. Hutchinson, Deputy Surveyor, under Contract #60, dated July 19, 1855 - (DCSO records Vol. 6 Page(s) 2470)</p> <p>-----</p> <p>Set post cor. to secs. 10, 11, 2 and 3. Drove charred post, dug trench with mound and pits as per instructions.</p>
<p>GLO survey by W. H. Byars, Deputy Surveyor, under Contract #376, dated Jan. 22, 1881 - (DCSO records Vol. 6 Page(s) 2528)</p> <p>-----</p> <p>Set Fir post for cor. to secs. 3 and 10. No trees convenient, made mound as per instructions.</p>
<p>John M. Phillips - Snellstrom Lumber Co. - March 1958 - C.S. File 42/350</p> <p>-----</p> <p>Sec. corner for 3 and 10 only, set by computation as recommended by Berlin in his letter of July 18, 1957. (See C.S. File for letter and other information)</p>
<p>Douglas County Surveyors Office - Milo Godfrey and crew - C.S. File 52/125-25 - Jan. 1966</p> <p>-----</p> <p>Corner searched for, not found.</p>
<p>Douglas Co. Surveyors Office - F.L. Ingram and crew - Jan. 1973 - C.S. File 56/24</p> <p>-----</p> <p>Found brass cap mkd. LS 307 T23S R7W $\frac{S\ 3}{S10}$ 2</p> <p style="text-align: center;">1957</p> <p>Brass cap out of ground. Two BTs, NW. and SW.</p>
<p>Douglas Co. Surveyors Office - L.E. Monrean, Deputy - R.W. Smith, crew - Wit: Roger Fearn, U.S. National Bank - Dec. 4, 1985 - C.S. File 62/29-4</p> <p>-----</p> <p>DID NOT FIND - CORNER REPORT ONLY Original monument not found. Found monument per C.S. File 42/350, loose, on top of ground and badly bent, an iron pipe and brass cap monument apparently set by John Phillips. The point where established by Phillips indeterminable. 28" W.Oak bears N.20°W., 142.7 ft., opened upper blaze, scribe found "30 B" visible in partially opened blaze. Blaze about 6" deep into tree. (Cont. Next Page)</p>

TOWNSHIP 23 RANGE 07 POINT IDENTIFIER # 500600

PRIMARY CORNER DESCRIPTION Sec Cor for 3 and 10 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

32" W.Oak with two healed blazes, bears S.27°W., 199.6 ft.
Tree has wire grown in on southerly side from random E-W fence.
We could find no record to reference trees to monument position. Since Haines' location of original corner to the South, the Phillips position of this corner may be questionable.

Fd. BTs, no distances given, by Carl Sweeden 2/2006 - M154-12