

PRIMARY CORNER DESCRIPTION Pt. on NE. bdy. Wm. Bay DLC #38

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

Surveys of Donation Land Claims by - Dennis Hathorn, Deputy, dated June 8, 1857 - DLC Volume, Page 142 ----- Set post, from which An Oak 12" dia., bears S.4°E., 665 lks.	
Arnold G. Gibson, Asst. Engineer, Oregon State Board of Forestry - April 22, 1957 - C.S. File 42/258 and M 5-19 ----- Found - Original post missing. 12" Oak bears S.4°E., 665 lks., now missing, rotted root stubs and logs in vicinity. Set 1½" x 36" galv. iron pipe with 3" bronze cap mkd. "Oregon State Board of Forestry T23S R8W AP DLC 38 S1 1957 RS 359", 35" in ground, in fence line at angle point (N.49½°W. and S.36½°E.) and from which a: 14" Oak bears N.7°W., 35.3 ft. scribed AP S1 BT. 26" Fir bears N.53°W., 105.6 ft. scribed AP DLC 38 BT RS 359. Center concrete boxed spring, bears N.61½°W., 75.4 ft. Set 4"x4"x72" white painted cedar post 1.5' NW. of pipe OSBF metal location poster on 12" Ash, N.47½°W. 25.7 ft	
Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 7/18/2002 - C.S. File 66/34-21 ----- Found - 1957 OSBF brass cap iron pipe 2" below ground. 4"x4" Cedar post now gone. 1961 12" Ash now 16" Ash with location tag in a NW'ly running fence line <u>we single blaze 3 ft. above ground & scribe "AP DLC 38 CS BT"</u> center of root crown bears N.48½°W., 26.7 ft. (rec. N.47½°W., 25.7 ft.) Center of 4½"x4½" concrete spring box bears N.61½°W., 75.4 ft. 26" now 40" dia, 3 ft. high D.Fir stump with a fully healed blaze, bears N.54½°W., 107.0 ft. (rec. N.53°W., 105.6 ft.) 14" Oak now tipped out of ground rotted Oak bears N.7°W., 35.3 ft. OBT not looked for. New - 27" dia., D.Fir double blazed & scribed "AP DLC 38 CS BT" bears N.83½°W., 23.4 ft. Corner is approx. 5 ft. Easterly of NW'ly running fence line, area E'ly of fence is clear cut. 14" dia., W.Oak double blazed & scribed "AP D:C 38 CS BT" bears N.14½°W., 17.0 ft. Compass Decl. 17¼°E.	